## SURVEY & REMONUMENTATION

APR 2 4 1995

## OTTAWA COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

9L DEC 15 AM 11:52

RECORDED

For corners COMMISSION

Ottawa		Located In:	Corner Code ##
	(County)	Crockery Twp.	
1.	Public Land Survey	Т <u>8N</u> R <u>15W</u> Т R	D-3 N. 1/4 Corner
		T R	Section 8
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

Physici Wademan REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_ 4. Lot No. Private Claims \_

i Carl P. Englert, in a field survey on December 2 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

8 9 10

A. Description of original monument and accessories and/or subsequent restoration: D-3 1/4 corner common to Sections 5 & 8 Original Gov't corner set March 1837

by John Mullet D.s.

Set 1/4 Section Post

B. Ash 6" N65°W 8 Links

B. Ash 7" N79°E 18 Links LCRC Liber 3, Page 224 (11/4/77) D-3) Replaced Rubber coated rod with Cast Iron Monument Inscribed "Ottawa County Section Corner.

Concrete Monument S 33.24 NE Corner House Porch SW 97.54

Power Pole

SW 108.40

See Back of Page

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-3 1/4 corner common to Sections 5 & 8

Found 4" CIM with Broken Top 4" deep 2.5' N of Road &

Found N. corner House Porch S.W. 97.54'

Found Conc. Monument S33.24'

Found P.P. S.W. 108.4'

P.A. 345 OTTAWA COUNTY

PEER APPROVED

Accepted as a careful and faithful perpetuation of the

original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

D-3 1/4 corner common to Sections 5 & 8

4" Harrison Cast Iron Mon.

O.C. Remon. Tag & Nail in S. side P.P.

O.C. Remon. Tag & Nail in S. side P.P.

O.C. Remon. Tag & Nail in S.W. side 16" Beech

Conc. Mon.

N38°W 166.27'

S720W 108.43'

S710E 58.55'

33.24' South

\_ Date \_\_\_\_\_

HARMAN HARMAN HARMAN THE CARL D ENGLERT JR. **PROFESSIONAL** SURVEYOR No. LAMONO

Carl P. English Surveyor's Michigan License No. \_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SONVENING JAN. 28, 1971

VISEO MAY 14, 1975 REVISED JAN., 1983

## LCRC Liber 1, Page 509 (6/26/72)

D-3		
FD 1/2" Rubber Coated Rob		
Elm Stump	SE	18.45'
Concrete Monument	S	33.24'
NE Corner Porch	SW	97.54'
Power Pole	SW	108.40'