## SURVEY & REMONUMENTATION

APR 2 4 1995

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AMII: 52

For comercioMMISSION

_0	ttawa (County)	Located In: Crockery Twp.	Corner Code #
1.	Public Land Survey	T <u>8N</u> R <u>15</u> W	_E-5
		T R	SE Corner
		T R	Section 8
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	<u> </u>


Phyllin Cademan REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

\_\_\_\_, Recorded Plat \_ 4. Lot No. Private Claims

I, Carl P. Englert, in a field survey on November 30 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

E-5 corner common to Sections 8,9,16 & 17 Original Gov't corner set March 1837 by John Mullet D.S.

LCRC Liber 6, Page 29 (12/26/89)

E-5 Set CIM

Set Post Hemlock 6" S48°W 10 Links Hemlock 10" N26°E 11 Links PР 28" Pine ENE 77.81 NE 62.94

12" Pine 18" Cherry NNE 89.53 SW 72.14

(See back of page)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5 corner common to Sections 8,9,16 & 17

Found 4" Harrison Cast Iron Mon. with broken top in Mon. box 1'+/- N. of Road

Found 30" Pine 62.19' NW Found 12" Spruce WNW 89.531 Found P.P. 77.81' NNW

P.A. 345 OTTAWA COUNTY

Accepted as a careful and faithful perpetuation of the original position of the corner.

PEER APPROVED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5 corner common to Sections 8,9,16 & 17

4" Harrison Cast Iron Mon. with broken top in Mon. Box S68°W O.C. Remon. Tag & Nail in N. side P.P. O.C. Remon. Tag & Nail in S. side 14" Spruce 143.77' N660W 89.491

N430W O.C. Remon. Tag & Nail in N.E. side 30" W. Pine 62.77' N130W 77.77 O.C. Remon. Tag & Nail in E. side P.P.

Signed by Carl P. Englect Ja Surveyor's Michigan License No.

LCRC Liber 1, Page 543 7/20/72 E-5 Iron Stake

S.S.E. 25.23 Twin Cherry S.W. 8" Pine 27.09 N.W. 30" Pine 63.38

LCRC Liber 1, Page 507 6/28/72 E-5 Found 1" Iron 20" Cherry SSE 25.23' 7" Pine SW 27.10' 30" Pine NW 62.19'