SURVEY & REMONUMENTATION

APR 2 4 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AMII: 49

Physica Redoman REGISTER OF DEEDS

For	cornare	in	

4. Lot No.

5. Private Claims __

_	Ottawa (County)	Located In: Crockery Twp.	Corner Code ##	OTTAWA COUNTY, MI
1.	Public Land Survey	T <u>8N</u> R <u>15W</u> TR TR TR	F-3 N 1/4 Corner Section 9	
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

I, Carl P. Englert, in a field survey on December 02 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-3 1/4 corner common to Sections 4 & 9 Original Gov't corner set March, 1837 by John Mullett D.S.

__ , Recorded Plat __

Set 1/4 Section post Beech 14" S63°E 14 Links Beech 11" N 70W 12 Links LCRC Liber 4, Page 128 (11/11/80) Fd. Angle Iron

Set Cast Iron Monument

Railroad Tie Fence Post South 25.07 25" Tree ENE 50.77

15" Maple Power Pole

34.72 NNE 50.79

North

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-3 1/4 corner common to Sections 4 & 9

Found 4" Harrison CIM with broken top 6" deep in road &

Found R.R. tie F. Post South 25.07'

Found 25" Tree ENE 50.77' Found 15" Maple NNE 34.72'

Found P.P. North 50.79'

P.A. 345 OTTAWA COUNTY

Accepted as a careful and faithful perpetuation of the Mulay D. Villey original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the comer:

F-3 1/4 corner common to Sections 4 & 9

4" Harrison Cast Iron Mon. with broken top O.C. Remon. Tag & Nail in N. side R.R. Tie F.P. 24.96' S10°W N72°E 51.31' O.C. Remon. Tag & Nail in S. side 28" Ash O.C. Remon. Tag & Nail in E. side P.P. O.C. Remon. Tag & Nail in SW side 12" Birch N 30M 50.971 N72°W 71.21'

CARL P. CARL P. C. ENGLEST " FORM APPROVED BY MICHIGAN STATE BOXER OF TANK SURVEYORS AND THE STATE BOXER OF TAND THE STATE BOXER OF TANK SURVEYORS AND THE STATE BOXER OF TANK