

RECORDED

94 MAY -6 AM 10:55

OTTAWA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

*Robert Blanton*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

OTTAWA  
(County)

Located in: \_\_\_\_\_ Corner Code # \_\_\_\_\_

1. Public Land Survey T 8N R 16W G-3 SW Corner  
T \_\_\_\_\_ R \_\_\_\_\_ Section 3  
T \_\_\_\_\_ R \_\_\_\_\_ Spring Lake Twp.  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, THOMAS E. JOINER in a field survey on APRIL 11, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

03-30-1837	Liber 1, Pg. 777, 12-04-72
Post set by John Mullet	Liber 5, Pg. 132, 06-27-84
N17°W 18 20" Beech	Set Cast Iron Monument
S70°E 12 15" Beech	SW 48.45 Light Pole
	NW 48.16 Telephone Pole
	NE 70.30 15" Walnut
	ENE 74.00 Power Pole

SURVEY &  
REMONUMENTATION

OCT 24 1994

COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Cast Iron Monument in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

NW 48.16 Telephone Pole  
NE 70.30 15" Walnut  
ENE 74.00 Power Pole



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Cast Iron Monument in Monument Box		
⊕ Top Bolt Fire Hydrant	Az. 39°04'	52.63
O.C. Remon. Tag & Nail in East Side Power Pole	Az. 323°31'	47.78
O.C. Remon. Tag & Nail in East Side Power Pole	Az. 223°07'	49.18
O.C. Remon. Tag & Nail in West Side 12" White Pine	Az. 130°05'	74.67

OTTAWA COUNTY  
PEER APPROVED 4/18/1994  
*Walter D. Hedwood*

Signed by Thomas E. Joiner  
Surveyor's Michigan License No. 18435

Date 4-15-94