APR 2 9 1996

## COMMISSION

		LAND CORNER RECORDATION CERTIFICATE						<b>.</b>
Fo	r corners in	Filing Rec	uirement of Act 74, N	₩.	COLUMN TO THE PROPERTY.	•	05/09/9! 13:49	00
0n	tonagon	Located In:	Corner Code ≠	# LC	3/ 263	JEM Fee: Page	_	սս 1
	(County)					F 63₹	LOT	•
1.	Public Land Survey	т 49N г 38	W J-1					
•	r delio Edito Guivoy	T R						
		T R		1				
		T R						
2.	Property Controlling	S T R						
	in Section	S T R						
3.	Miscellaneous	S T R			Register of De	eds Stamp &	File Numb	er
	Property in Sec.	S T R						•
4	Lot No.	Recorded Plat						
					A B	COEFG	H I J	K Ł
Ų.	1/4 Corner Secti	ons 2 & 35; T.49-50	N., R.38W.	<u>r</u>	2 - 6 -	-5		
					3	<del></del>		
	Di Lante Di I	44			4 - 7		-10-11-	-  2
		, in a field survey on Ma	•		5			+
	, ,	quirements of P.A. 74, Michigan in conformance with regulation	•		618	-17-16-	1514-	- - 3
		uctions of the United States D			7			-  -
	•	a Court of Law and/or that the o			8 19	_2021	2223	
		ith the rules of the Michigan Bo re-established, monumented,			9			11
	pressed below:	Te-established, monumented.	re-monumented, recovere	ou, round as	10_30_	-29 -28	_2726_	
NC	TE: Not more than 4 o	orners, all in the same tow	n and range, may be re	corded	11			11
	on this certificate				1231	3233	_3435_	J-36
•	•				13			
A.	Description of original	monument and accessories	and/or subsequent res	toration:				
	Corner establish	ed by Austin Burt,	U.S. Deputy Surve	vor. on Ji	me 24, 18	47. Origi	nal	
	bearing trees:	<b>3</b>		, . ,		0, 191	.,	
	Cedar	12"	N.36E.	50 1	inks	(33.00 fee	et)	
	Y. Birch	. 10"	N.08W.			( 7.92 fee		
	,							
В.	Description of corner of	evidence found and/or meth	od applied in restoring of	or reestablish	ing corner:			
		_						
	No original evid	ence remains, corner	r established on	line betwe	en and eq	ual distan	ice from	
	the NE & NW sect	ion corners of Sect	ion 2; T.49N., R.	38W.			<b></b>	
		•	•				SI COMPANY	
						AT	116	<b>A.</b>
	•		ONTONAGO?	I COUNT?		RICHA	DO NA	<b>14</b>
		• •			•	* L. DRA		* <b>*</b>
			PEER APP	KOAÉD	I	* LAN	D	* 2
			Part W Go	plekany		SURVE		. ž
	·		Ontono	6 6	o 🐧	No. 2156	<i>•</i> . "	3
			Larl W Up Ontonagon Mas i	1000	7			F
	•		91/av 6	11783		MAN D LAT	10 50	-
_	B. odeka okusa		in actablished to perso	tuata lacatina	the position	of the course	Manager.	
C.		ent for corner and accessor						
	At the corner po	sition and 6" below	the surface of a	n E-W road	l set a :	2" x 12" c	oncrete	
	filled galvanize	d iron pipe with a :	3" brass cap, star	mped to re	ead: T.49-	50N., R.38	W.; 1/4	•
	5-2, 5-35; 1994;	R.L.S. 21564; from	which I establish	ned the fo	ollowing:	A 2 1/2"	x 30"	
		th a 3 1/4" aluminum	m cap stamped to	indicate i	the corner	s location	bears;	
	North, 30.54 fee 6"		N AALC		10.05.6			
	10"	Red Pine	N.34W.		42.85 fee			
	10" 10"	Power Pole Power Pole			48.35 fee			
	6'	Steel Rail	S.51E. North		49.50 fee	-		
	U	Steel Kall	NOTER		30.54 fee	ī.		
	- 1	1 10 10 0		- A		005		
Sia	ined by Rickar	ed L. Deal	<u> </u>	ate Feb	ruary 8, 1	995		
		01564						
Su	rveyor's Michigan Licens	se NO		FORM	APPROVED BY MICHIGA	N STATE BOARD OF LAN	L ,REVEYORS DI A GESIVER	
	USFS #A-19		263					O JAN , 1
			NOI					