LIBER 329 PAGE 607

1998 Presque Isle County State of Michigan Land Corner Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich	
Presque isle County Located In: Corner Code # Round: Bismarck	PRESQUE ISLE COUNTY RECORDED
1. Public Land Survey	98 NOV 25 AM 11: 16
TR	REGISTER OF DEEDS Register of Deeds Stamp & File Number
4 Let No. Decorded Dist	
4. Lot No, Recorded Plat	In and for 6 18 17 16 15 14 13 18 18 18 18 18 18 18 18 18 18 18 18 18
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
The selection of existent manufact and acceptate and for subconsent restoration.	13
A Description of original monument and accessories and/or subsequent restoration: J-1 SEE	REVERSE SIDE OF SHEET
	CONTINUATION PART "A" SURVEY & REMONUMENTATION
•	JAN 1 4 1999
B. Description of corner evidence found and/or method applied in restoring or reestable J-1 Found boat spike in centerline of East-West tar	ishing corner: SECTION
surfaced road Found all witnesses from August 16, 1994	m 110 11 . D O
recordation	Ratified by Peer Group in accordance with P.A. 345
Set 1 additional witness;	
N 60°E 58.51°, P.S. 21559 tag in 6° Elm	Chairman Month of Classical Date 7/2/08
C. Description of monument for corner and accessories established to perpetuate locating of Boat spile in centerline of East-West tar surfaced road Witnesses: S45*W 68.43*, J. Nelson tag in near face of fence post S25*E 46.39* NW Cor. Garage S62*E 89.70*, J. Nelson tag in power pole N30*W 36.91* near face of metal pipe road sign post N 60*E 58.51*, P.S. 21559 tag in 6* Elm	JAMES A. BECK LAND SURVEYOR No. 21559
Signed by James C Seek Da	te October 5, 1998
Surveyor's Michigan License No. 21559	
FORM APPROVE	D BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

1998 Presque Isle County, State of Michigan Remonumentation

Bismarck Township, T34N, R4E

Corner code: J-1 N 1/4 Corner Section 2

PART "A" CONTINUED

July 20, 1976 P.A. 74 (Land Corner Recordation Certificate) by John Nelson No. 21273

<u>Part A:</u> "Witness from Highway Plans #CS71-33 RS747-103 by Scott Engineering Co., Inc."

Part B: Set 5/8" Re-rod w/R.L.S. Cap from above witnesses. Corner is in centerline of Heythaler Highway (30' gravel to East and 20' asphalt to West) and in line with Aspin Road (12' gravel) to South. Previous Corner apparently obliterated during road reconstruction.

Corner fits abandoned R.O.W. to North.

Part C: 5/8" re-rod with Cap

Set Nail w/R.L.S. Tag in Northwest side telephone pole Az. 66° 86.17'
Set Nail w/R.L.S. Tag in Northeast side utility pole Az. 117° 90.01'
Set Nail w/R.L.S. Tag in East side fence post Az. 230° 68.55'

(Highway plans witness call)

August 16, 1994 P.A. 74 (Land Corner Recordation Certificate) by James A. Beck No. 21559

<u>Part A:</u> Recorded 7-20-1976 by J. Nelson R.L.S. 5/8" Re-rod

Az 66° 86.17 ft RLS 21273 tag in NW side utility pole

Az 117° 90.01 ft. RLS tag NE side utility pole

Az 230° 68.55 ft. R.L.S. tag E. side fence post

Part B: "Found boat spike

see witnesses below."

Part C: North 1/4 corner Sec. 2, T34N, R4E

Found boat spike

S45°W 68.43', J. Nelson tag in near face of fence post

S25°E 46.39' NW Cor. Garage

S62°E 89.70', J. Nelson tag in power pole

N30°W 36.91' near face of metal pipe road sign post