PRESOUE ISLE COUNTY RECORDED

COMMISSION

*Witness tags and nails used.

LAND CORNER RECORDATION CERTIFICATE

93 DEC 20 PH 4: 48

For corners in	Filing Requi	irement of Act 74, I	Aich. P.A. 1970	Junet -	m. Lam	4
PRESQUE ISLE	Located In:	Corner Code ≠	4 l	77	ER OF DEEDS	
(County)	Located in:	Conter Code	7	MEGIO:	en or pero.	,
Public Land Survey	T 34N R 2E T R T	A-2		LIBER 30'	7page 87 0)
, ,	T R					
	T R					
	T R T R		Reg	ister of Deed	s Stamp & Fil	e Number
-,			•			
4. Lot No, Recor				A B C	DEFGH	JKt
5. Private Claims				2 6 - 5		
				3		
				4 7 7		
Ronald R. Bischer, in	6 1 1	aust 30	10 93	5	,	
do hereby certify that under requires	a field survey on au	A. of 1970, the corner poi	nts mentioned	1 1		
in lines 1 and 2 above were in con	formance with regulations a	and rules therefore as re	equired in the	6 -181	71615	14
current manual of survey instruction	ns of the United States Dep	artment of the Interior, B	ureau of Land	7	- - - - 	
Management or by a decree of a Cou above were in conformance with the	ort of Law and/or that the cor	ner points mentioned in II	nes 3, 4 and 5	8 - 19 - 20	02122	
Court of Law; established, re-est	erules of the Michigan Board tablished, monumented, re	e-monumented, recover	ed, found as	9	- - - - 	
expressed below:			•	10 30 2	9 28 27	
NOTE: Not more than 4 corne	rs, all in the same town	and range, may be re	corded	11		
on this certificate.				12	2 33 34	35;
				13		
A. Description of original mone	ument and accessories a	nd/or subsequent res	toration:			
June 2, 1840 John Hodgson set Woo 12" Cedar S28°W 19 18" Cedar N75°W 33 1976 - Delmar E. Port Set ½" Rod by Single South 45.90' Cente	5 links 2 links er e Proportion	S45°W 34.92'N89°W 48.61'Recorded on Pa September 22,	Fence corne ge 151, Land	r	ion,	
B. Description of corner evide		dapplied in restoring	or reestablishing	corner:	and 30-	
A-2 Found ½" Rod and Cap	#15410 buried 1.2 Corner bad sign byed, sign gone. rline North Rail	,		St. Committee of the St. Commi	RONALI BISCHIS LAND SURVEYO NO. 22428	
C. Description of monument for A-2 ½" Rod and Cap #15410 N81°W 48.64' Fence S38°W 48.67' Post i) Corner		Ratified by Po	eer Group	245 .	
S77°E 45.02' 4" Ced		T+1C	III accordance	0.1	18 Porter	J
N87°E 43.02 4 Cec			Chairman 4	Lunes	100	
			Chairman Date	omba /	144.3	

Signed by Royald R	Birthe	Date	./3-93
Surveyor's Michigan License Ng.	_		

CORNER HISTORY RESEARCH SHEET

A-2 Corner,	Section 6	Township 34N	Range <u>2E</u>
			•

Activity

1840 Original Survey John Hodgson

1976 Delmar E. Porter #15410

1993 Remonumentation Ronald R. Bischer #22428

Monument & Accessories

Wood Post Set 12" Cedar S28°W 15 links

18" Cedar N75°W 32 links
Set ½" Rod & Cap #15410 by
single proportion

Set 3 witnesses

Found ½" Rod & Cap #15410
N81°W 48.64' Fence corner
found nail w/tag #15410
S38°W 48.67' Post in old RxR
centerline
set nail w/tag #22428
S77°E 45.02' 4" Cedar
set nail w/tag #22428
N87°E 51.31' 4" Cedar

set nail w/tag #22428

Comments ·

*5'/