____ , Recorded Plat _

COMMISSION

For corners in

4. Lot No.

5. Private Claims ___

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 20 PH 4: 48

PRESQUE ISLE	Located In:	Corner Code ##	REGISTER OF DEEDS
1. Public Land Survey	T 34N R 2E	<u>A</u> –3	•
	T R		
	T R		
	T R		
2. Property Controlling	\$ T R		-
in Section	S T R		LIBER 307 PAGE 872
3. Miscellaneous	S T B		Parista of
Property in Sec.	\$ T R		Register of Deeds Stamp & File Number

I, Ronald R. Bischer, in a field survey on August 30 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

10 11 12

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-3June 2, 1840 John Hodgson set Wood Post 6" Beech SO4°W 26 links 6" Beech N83°W 23 links 1978 - Delmar E. Porter Found 1" Bar in Monument Box Recorded on Page 260, Land

Recordation, September 29, 1978. N40°E 68.80' Fence corner S45°E 63.05 Telephone pole S45°W 65.15 Telephone pole Clifford Lindgren (#14098) replaced 1" Bar with 2" Rod at an unknown date.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-3Found 1/2" Rod and Cap #14098 in Monument Box \$35°E 63.73' Telephone Pole S41°W 64.97' Telephone Pole



COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

S35°E S41°W N25°E N24°W	62.73' 64.97' 74.83' 66.83'	#14098 in Telephone Telephone Telephone	pole pole pole	Ratified by Peer Group in accordance with P.A. 345 Chairman Alehan Efrata Date Accorder 7, 1993
*Witnes	se tame a	nd naile i	ഭരദ്	

Signed by Ronald R. Binham	Date /Z -/3 - 93
Surveyor's Michigan License No. 22428	

Township 34N Range ZE A-3 Corner, Section 6,7

<u>Activity</u>

1840 Original Survey John Hodgson

1978 Delmar E. Porter #15410

1993 Remonumentation Ronald R. Bischer #22428 ,

Monument & Accessories

Set Wood Post 6" Beech SO4°W 26 links 6" Beech N83°W 23 links

Found 1" Bar in Monument Box Set 3 witnesses Recorded on Page 260, Land Recordation, September 29, 1978

Found ½" Rod & Cap #14098 in Monument Box S35°E 62.73' Telephone Pole found nail w/MSHD tag S41°W 64.97' Telephone Pole found nail w/tag #15410 N25°E 74.83' Telephone Pole set nail w/tag #22428 N24°W 66.83' Telephone Pole found nail w/tag #15410

Comments .

Clifford Lindgren replaced 1" Bar with 2" Rod at an unknown date.