

1067

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Presque Isle Located In: _____ Corner Code # _____
(County)

- 1. Public Land Survey T 34N R 5E _____ C-9
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

PRESQUE ISLE COUNTY
RECORDED

96 JUN 13 PM 12:25

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Ronald Bischer, in a field survey on 3-14, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-9
1856 Alfred Millend Set Wood Post
N23°E 43 Links 12" Hemlock
S48°W 27 Links 11" Cedar
12-6-84 Delmar Porter set 1/2" rod in road centerline @
Int. section line fences
left 3 witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9
3-14-96 Ronald Bischer found 1/2" Rod & Cap #15410
S78°W 77.51' 8" Apple
S34°E 39.08' 4" Cedar
N11°W 61.98' R. Pine



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9
3-14-96 Ronald Bischer
1/2" Rod & Cap #15410
S74°W 77.51' 8" Apple
S38°E 39.08' 7" Cedar
N11°W 61.98' 6" R. Pine
N13°E 63,82' 4" Cedar

Ratified by Peer Group
in accordance with P.A. 345
Chairman *John E. Pate*
Date 6/12/96

Signed by Ronald R. Bischer Date 6-6-96
Surveyor's Michigan License No. 22428