## APPROVED BY PEER GROUP LIBER 1925 PAGE 1149 P.A. 345 OF 1990 SAGINAW COUNTY REMONUMENTATION SAGINAW COUNT Filing Requirement of Act 74, Mich. P.A. 1970 Syber 6 Page 27 For corners in Saginaw REMONUMENTATION In: Corner Code ## RECORDED (County) Public Land SuAPR 2 4 1995 T 11N R 4E COMMISSION Т R 63715 **Property Controlling** Τ. S \_\_ T \_\_\_\_\_ R . in Section Miscellaneous \_\_\_ T \_\_\_\_ R \_ Register of Deeds Stamp & File Number Т Property in Sec. \_ , Recorded Plat \_ Private Claims Duane F. Ledy July 28 in a field survey on . 19 \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 9 Court of Law, established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 13 Description of original monument and accessories and/or subsequent restoration: Set post at intersection with township line 5 links east of K-13, J. Wampler, 1822. City of Saginaw 1922 resurvey maps show position of monument at 3.53' east of K-13. Robert Tommer Jr. survey in 1976 indicates a found cast iron monument in monument box, L1783, P197. Survey by Hammond in 1978 indicates a monument found giving witnesses (calls for mon. box 37.0' west, appears it should be 3.70' west) L1558, P935. M.D.O.T. ROW plans show monuments existing 3.65' apart, the east being K-1. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 2" City of Saginaw cast iron monument in monument box. Found witnesses in recorded instruments as follows: West 3.71' to City monument in box (3.53' City, 3.65' M.D.O.T.). N.E. 32.00' to PK nail in side of PP (31.5' N 40° E to face PP). S.E. 84.4' to PK nail in side of PP (84.0' S 25° E to face PP). Position of existing monument accepted as best possible position of original corner. Position accepted by Saginaw County Peer Review Group on December 7, 1994. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Stamped top of 2" cast iron monument with 21575, monument in monument box. West 3.71' to 2" cast iron City monument in monument box (K-13). 32.00' to PK nail in utility pole. N 45° F N 45° W 50.15' to PK nail in utility pole. S 45° E 84.40' to PK nail in utility pole. S 45° W 50.62' to top center nut on fire hydrant

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED MAY 14, 1975 REVISED JAN., 1983