,				
A BOOMED DV DEED ODOUG	_			
APPROVED BY PEER GROUP P.A. 345 OF 1990 SAGINAW COUNTY	Saginaw County	Remonumentation	.925 PAGE 323 ESIBLUG PAG	x249
10 1-11 101	Filing Requirement	of Act 74, Mich. P.A. 197	0	73
For corners in		· · · · · · · · · · · · · · · · · · ·	SA RE	EO
Saginaw SURVEY & oc	ated In: Co	rner Code ##	Sec. 1	S _A
REMONUMENTAT	ION			n Ha
1 Public Land Survey T	19N □ 9F N	1 12		. 569
APR 2 4 1995 T	R			RECORDED & FILED
			Zm2	
2. Property Controlling MMISSION			HOS SO	皇
in Section S T. 3. Miscellaneous S T.	8 		·	
Property in Sec. S T	R	R	egister of Deeds Stamp & I	File Number
Lot No, Recorded Plat . Private Claims			ABCDEFG	HIJKL
	**		- 2 6 5 4	3
			3	}
, Craig W. McVean , in a field sun	tuno 15	04	⁴ ├─ ├─┼─ \$ ─ ┼─ 	10-11-12-
do hereby certify that under requirements of P.A.	A. 74. Michigan P.A. of 1970, tl	he corner points mentioned	5	
in fines 1 and 2 above were in conformance of current manual of survey instructions of the Ui	with regulations and rules th	erefore as required in the	7 18 17 16	15-14-13-
Management or by a decree of a Court of Law ar			8 10 20 21	
above were in conformance with the rules of the Court of Law; established, re-established,			9	222324
expressed below:	monumented, re-monumen	ted, recovered, round as	10 30 29 28	272625
NOTE: Not more than 4 corners, all in t	he same town and range	, may be recorded	11	
on this certificate.			12 31 32 33	34-35-36-4
A. Description of original monument and	accessories and/or sub:	sequent restoration:	13	
M 12 Set 1/4 Section post - J. Wampler		·	und 1/2" rod - Leach - 1978.	
W. Oak 30" N 22° W 10 L.	-	LCRC - L. 1632, P. 201	8 - found 3/4" iron pipe 12.45	
Lynn 9" S 11° E 2-1/2 L.			ection 31, T12N, R3E - also fou bove 3/4" pipes and 1.22' N. o	
Dow Chemical/Spicer Engr. Survey and		S'ly pipe. This appears	s to be the points recorded in	Section A.
- roof nail in bituminous surface by nail in line with fence to W.) - 1957.	Cooper (notes show	above (1/2" rod per LCi 1982.	RC L. 2, P. 167 and L. 4, P. 167	7) Prevost -
LCRC - L. 2, P. 85 - set 1/2" iron fence line agrees with government		Recorded Surveys - L. 1	1386, P. 182 - 1973; L. 1552, P.	237 - 1978;
ieure une adrees mitt dozeniwent	ausvey rocarron in	L. 1636, P. 249 - found	UA TOU - 1903.	

McKelvey - 1972.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M 12 Standard 1/4 corner common to Section 36, T12N, R2E found 3/4" I.D. iron pipe per Dow Chemical/Spicer Engr. survey and LCRC L. 4, P. 167 in line with fence to West. Excavate 3/4" x 0.9' iron pipe and find old roof nail by Cooper per Spicer notes and several small pieces of red fire clay. Monument accepted as the best available evidence of the position of the original corner.

relation to W. 1/4 corner of Section 31, T12N, R3E -

Reference Pt "A" - Found 1/2" rod per LCRC L. 2, P. 85 and L.4, P. 167 and per recorded surveys L. 1386, P. 182 (Doyle, Kelly & Assoc.); L. 1552, P. 237 (Leach Engr.) and L. 1636, P. 249 (Edmands Engr.) 1.22' N. of M 12. Monument was established using improper procedures and is not utilized as M 12-T12N-R2E in this survey. Replaced 1/2" rod with pk nail.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M 12 Replace 3/4" pipe and roof nail with 2-1/2" Saginaw County brass cap on 5/8" x 18" rebar in mon. box.

S 25° W 32.44' to capped 3/8" rebar.

N 83° W 57.53' (57.2' -R) to set nail and tag in S. side U.P.

N 12° W (N 15° W -R) 63.80' (63.85' -R) to found chiseled "x" on E. side concrete M.H.

N 40° W 196.24' to nail and tag in NE, side 40" Poplar.

North 12.40' (12.45' -R) to A 12-T12N-R3E.

North 1.22' to Reference Pt "A".

CRAIG W.
MCVEAN
PROFESSIONAL
SURVEYOR
NO.
39088

12/17/94