RECORDED

. .

& FOLED

SAGINAW COUNT

Property in Sec.

P.A. 345 OF 1990 SAGINAW COUNTY REMONUMENTATION PROJECT

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 14 4 06 PH '91

REGISTER OF DEEDS SACINAW COUNTY MICH

SURVEY & For corners in Saginaw REMONUMENT STROW

Corner Code #

1. Public Land Survey R 2 4 1995 12N R 3E COMMISSION R

2. Property Controlling R in Section 3. Miscellaneous

Liber 6 Page 221

Register of Deeds Stamp & File Number

8

17

20

29

32

2 3

4

5

6

0 10

11 12 31

18

19

30

CDEFGHIJK

10

15

22

27

34

14

23

26

35

12

13

24 (

25

36

0

16

21

28

33

4. Lot No. , Recorded Plat 5. Private Claims

, in a field survey on October 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- Standard E 1/4 cor., Sec. 24, T12N-R3E
 Wood post placed by J. Wampler, Deputy Surveyor 1822 (N-8)78 lks. (51.48') 11" Maple No record of subsequent restoration

1958 Consumers Power Company survey by M.D. Stitt, C.P. Co. called "M-8", T12N-R4E, & "A-8", T12N-R3E a common corner. Drawing No. S-F16228 rev. F sheet 13

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (M-8)Standard E 1/4 cor. Sec. 24, Standard E 1/4 cor., Sec. 24, TIZN-KJE Found no evidence of original government corner. T12N-R3E

Found C.P. Co. iron on so-called E-W 1/4 line 85.84' West of M-8 as per record stated in "A" above. C.P. Co. used K-8 & L-8, T12N-R4E, extended Easterly to the point of intersection with the Township line between M-7 & M-9. C.P. Co. then called M-8, T12N-R3E, & A-8, T12N-R4E a common corner. This call is in disagreement with the original government notes as determined by the 1993 peer review group when reviewing A-8, T12N-R4E. See L.C.R.C. L. 1882 pg. 1679, Saginaw County Records. Therefore M-8, T12N-R4E, was reestablished using C.P. Co. information at the position as shown on C.P. Co. drawing as stated in "A" above, and is See L.C.R.C. L. 1882, accepted as the best available evidence of the position of the original corner.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Standard Section cor., Sec. 24, T12N-R3E (M-8)

rerod w/brass cap stamped Saginaw County Monument, Set 5/8"

P.S. #39096 in Consumers Power Company easement.

s07°E 48.861 1" nut welded to West base of transmission tower S84°W 99.181

Fnd. spike w/tag #12018 in N. fc. 8" Ash

S60°W 86.30 Fnd. spike w/tag #12018 in NW fc. 8" Ash

South 16.15' A-8, T12N-R4E

ausu Signed by Surveyor's Mighigan License No.

OF WO JOHN H. RADSFR PROF138IONAL **EULYZYOR** NICO C

And a subject of

ADAPTED FOR WORD PROCES