APPROVED BY PEER GROUP

LIBER 1925 PAGE 1165

	OF 1990
P A 345	THE TURNET I
1,77,070	Of 1000 13
CACINIANA	
>AL-INAW	H A HINN KYN I

SAGINAW COUNTY REMONUMENTATION

•	0 00
Likes 16	Page 284
Of we	

12-7-90/ LAND CORNER RECORDATION CERTIFICATE		
For corners in Saginaw Corner Code at 1	Dec 2	;
(County) SURVEY & Located In. Corner Code ##	73 73 73 73 73 73 73 73	
1. Public Land Survey 1. Public Land Survey 1. Public Land Survey 1. Public Land Survey	CORDED 29 9 3 DEC STERRITH AW COLLN	
APR 2 4 1995 T R T T R T T T R T T T T R T T T T R T T T T R T T T T R T	30 AH '9 30 AH '9 30 AK 'F DEEDS NTY MICH	
2. Property Control MISSION R R IN Section S T R R	DS SOL	
3. Miscellaneous S T R	gister of Deeds Stamp & File Number	
4. Lot No, Recorded Plat	A B C D E F G H I J K	L
5. Private Claims	2 6 5 4 3 - 2	Ţ~
	3 4 7 8 9 10 11	12
I, Duane F. Ledy , in a field survey on December 22 , 19 94 ,	5	1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	6 -18 -17 -16 -15 -14	-13~
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a	8 19 20 21 22 23	-24-
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	9 10 30 29 28 27 26	-25-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11	-36-
A. Description of original monument and accessories and/or subsequent restoration:	13	٠

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

City of Saginaw 1922 resurvey maps show position of M-11 as being 30.33' north of A-11. No recorded evidence of position being restored subsequent to City of Saginaw information.

M-11 No corner found.

No L.C.R.C.'s or surveys recorded to establish position of corner Corner reestablished based upon City of Saginaw resurveys 30.36' north of position of A-11 per G.L.O. Position accepted as best possible position of original corner. Position accepted by Saginaw County Peer Review Group on December 7, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11	Set 3 ^r	Saginaw	County	brass	cap on	5/8" x	18"	rebar	in monun	nent box.
<u> </u>	OCC O	Cagnian	County	01000	OGP OIL	V/ V		ICDUI	III THOMAS	HOLLE DOV.

16.5' to centerline Sheridan Road West

49.70' to PK nail in N.E. face of utility pole 68.90' to PK nail in S.E. face of utility pole N 50° W S 45° W S 50° E

M-11 Corner set at 80 chains north of M-13, J. Wampler, 1822.

9" Maple n 371/2° W 4.5 links. 36" W.Oak N 63° E 30.5 links

49.60' to PK nail in N.E. face of utility pole N 45° E

South

40.21' to chiseled "x" in west bolt of Little Caesars sign base

30.36' to Saginaw County Remonumentation cap (A-11).

Signed by Surveyor's Michigan License No. _

DUANE F.
LEDY
PROFESSIONAL
SUFFESSIONAL
AOFESSIONAL
SUFFESSIONAL
SUFFE FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983