FILED

004 PG 040

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Jun 27 12 47 PH \*94

Cypteisio a la mote
REGISTER OF DEEDS

for comers in	•		REGISTER OF BUEBS	
ST. JOSEPH	Located In:	Corner Code <i>≔‡</i> ≢	ร์ที่มีข้อสุดห้อดีไท่ดีห	
Public Land Survey	T <u>5S</u> R <u>10W</u> T R T R	<u>1 - 9</u>		
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	TR	SURVEY & EMONUMENTATION AUG 3 1 1994	Register of Deeds Stamp & File Number	
	Recorded Plat	COMMISSION	— A B C D E F G H 1 J K L M	
wayne A. Mostrom fo hereby certify that under ron lines 1 and 2 above were current manual of survey inst danagement or by a decree of above were in conformance would follow; established, expressed below:	in conformance with regulations a ructions of the United States Depa t a Court of Law and/or that the corr with the rules of the Michigan Board re-established, monumented, re corners, all in the same town a	MAY 13 19 94 A of 1970, the corner points mentioned nd rules therefore as required in the artment of the Interior, Bureau of Land the points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	2 6 5 4 3 2 3 4 7 8 9 10 -11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13	
A. Description of origina	monument and accessories ar	nd/or subsequent restoration:		
1876 SURVEY BY N.S.  ANDREWS PREVIOUSLY !  IN 1858 FROM OLD BE:  17" Y.O. = \$46°E 6  1974 L.C.R.C. (3/11  PIPE IN MON BOX  21" MAPLE = WEST 32	SET STONE PRINGS 2 1/2 LKS ) BY SAYERS	LCRC IN (1/29)  IRON FOUND IN MON. BOX 21" MAPLE = WEST 32.45"  SAYERS SURVEY IN 1960"S  SHOWS IRON SET 33" WEST  SAYERS 1977 SURVEY		

21" MAP = W. 32.45, HYD. = SE 49.1"

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<u>1 – 9</u>

TOP/FIRE HYD. = SE 49.1'

FOUND 1" IRON PIPE IN CONC. IN MON. BOX IRON = WEST 33'
FIRE HYD = SE 49.1'
21" MAPLE = WEST 32.45'

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 ON JUNE 13, 1994 Warm CO. REPRESENTATIVE

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9 (CORNER COMMON TO SEC'S 22, 23, 26, 27)

SET 5/8" X 3" BAR W/STD. CAP IN 1" IRON PIPE IN CONC. IN MON. BOX

TOP FIRE HYDRANT = S29°E 49.1'

NW COR OF CONC. BASE OF STONE PILLAR = S63°E 56.12'

N & W IN S. SIDE 32" MAPLE = N88°W 32.45'

N & W IN E. SIDE POLE = S16°W 79.56'

igned by Maryland De 14100

6/15/94

WAYNE A.
MOSTROM
PROFESSIONAL
SURVEYOR
No.
14100

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983

Burveyor's Michigan License No.

REMONUMENTATION