NOV 3 0 1993

## COMMISSION

\_\_\_\_ , Recorded Plat \_

## 004 PG 009

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 JUL 27 1 03 PM \*93

Cypitatio R. Lanott

corners in REGISTER OF DEEDS ST. 1985FH OF MICH ST. JOSEPH Located In: Corner Code :## FLOWERFIELD TWP. T 55 R 12W I - 7 **Public Land Survey** T \_\_\_\_\_ R \_\_\_\_ \_\_\_\_R **Property Controlling** .... T \_\_\_\_\_ R \_\_\_\_\_ in Section \_\_\_\_ T \_\_\_\_ R \_\_\_\_ Miscellaneous -S \_\_\_\_ R \_\_\_\_ Register of Deeds Stamp & File Number Property in Sec. \_ T \_\_\_\_ R \_\_\_\_

AYNE A. MOSTROM , in a field survey on \_\_\_JUNE\_9 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned ines 1 and 2 above were in conformance with regulations and rules therefore as required in the rent manual of survey instructions of the United States Department of the Interior, Bureau of Land nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a urt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

ITE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

.0 " W.O. = N67°E 1.61 CH " W.O. =  $N70\frac{1}{2}$ °W 1.45 CH

Private Claims \_\_

**186 SURVEY IN A/538** ONE FROM ORIGINAL REE STILL GREEN N67°E 1.61 CH.

1896 SURVEY IN A/730 FOUND STONE

10" BUTTERNUT = NW'LY 47 LKS 10" BLK. WAL. = NW'LY 57 LKS

ROAD COMM. - 1960'S STONE UNDER MON. BOX

A.P. = N04°E 35.6' A.P. = S42°E 36.1'

21" WAL. = N35°W 37.7"

L.C.R.C. 1/1 (1971) 24" WAL. = N40°W 37.95 10" WAL. = N30'E 37.45' TELE. POLE = \$45°W 41.70'

RUSHLOW IN 1992 FD. STONE IN MON. BOX 12" WAL. = N45°E 37.1"

10

11

TELE. RISER = N06°E 35' Description of corner evidence found and/or method applied in restoring or reestablishing conner HSE = N35°W 73.01

STO PILLAR = N45°W 74.0'

FOUND STONE IN MON. BOX REMAINS OF WAL. STUMP = N35°W 37.6' HOUSE COR = N30°W 73.07

Description of monument for corner and accessories established to perpetuate locating the position of the

SET STD. CAP ON 5/8"X24" IRON BAR IN MON. BOX OVER STONE

SE COR GAR. FTDN. = NORTH 142.90'

SE COR HSE. FTDN. = N30°W 73.071

SW COR HSE. FTDN. = N40°W 86.37'

NE COR. HSE. FTDN. = \$30°W 109.98'

COR. IS 1.6' SOUTH + 1.0' E. OF & -@

CORNER WAS APPROVED BY PEER GROUP 7/21/93 AS A PERPETUATION OF THE ORIGINAL CORNER.

veyor's Michigan License No.

Date 11 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

./01

MOSTROM

SURVEYOR

NO.

14100

PEO LAHO SUP