SURVEY & REMONUMENTATION

JUL 1 6 1998

SECTION

32339

Surveyor's Michigan License No.____

		O CORNER RECORDATION Requirement of Act 74, M		-	Total Barel
For corners in	, un	is requirement of Act 14, h	MCH. P.A. 1970	LIBER 🕽	PAGE 77
ST. JOSEPH	Located In:	Corner Code #			STATE OF MICHIGAN
FABIUS TOWNSHIP 1. Public Land Survey	<u>T.6s</u> R	1 <u>2W</u> <u>F</u> –8		2	ST. JOSEPH COUNTY FILED 6 JUN 1998 4:34:36 PM
	TR TR		ľ	-	n now 1330 4-74-70 LU
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		F	Register of Deeds	CYNTHIA L. JARRATT REGISTER OF DEEDS Stamp & File Number
4 Lot No Recor	tod Blot				
5. Private Claims	Jed Plat			BCDEF	GHIJKLM
				- 6 - 5 - 4	3 2 1
L DAVID II NOSTDAN			3 -		
I, <u>DAVID W. MOSTROM</u> , in a field survey on <u>JULY</u> , 19 <u>95</u> do hereby state that unde requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in				- 7 - - 8 - - 9	10 11 12
conformance with regulations and in United States Department of the In-	rules therefore as require iterior, Bureau of Land M	d in the current manual of survey insti anagement or by a decree of a Court	ructions of the	10 17 16	
that the corner points mentioned in	n lines 3, 4 and 5 above [,]	were in conformance with the rules of Law; established, re-established,	the Michigan	10 17 10	15 14 13
recovered, found as expressed belo	ow:		8	-19	22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9		
on this certificate.			10	-30 29 28 -	27 26 25
			11	-313233	34 35 36
A 50 7 11 A 1 1 1			13		
		es and/or subsequent restoration			
*1864 SURVEY IN BOOK A, SET STONE AT INT. OF 18" W. OAK = N39°W 3.9	1/4 LINES (96' (6	1974 SURVEY BY MOSTRO LCRC IN BOOK 1, PG. 1 FD. PIPE IN MON. BOX CORNER FALLS IN CENTE BROADWAY & A.L. JONES 1/2-1/4 COR. = WEST 1 1/1/4 COR. = WEST 2638	17 LABE EAST RLINE OF SOUTI RD. 319.05'	LED OR WITNE 1/4 COR. =	EAST 2631.311
B. Description of corner evide	ence found and/or me	thod applied in restoring or reest	ablishing corner		
FOUND 3/4" PIPE IN MON	. BOX OVER STO				
CENTERLINE BROADWAY = CENTERLINE A.L. JONES	SOUTH 1.5'	%1			
1/2-1/4 COR. = WEST 13	18.35'	J	RATIFIED	BY PEER GR	OUP
WEST 1/4 COR. = WEST 2 EAST 1/4 COR. = EAST 2			IN ACCOR ON Jun	(DANCE WITH	P.A. 345
SOUTH 1/4 COR. = SOUTH	2629.98		CORM	CO. REPRESE	, 1998 NTATIVE
SET 5/8" X 24" IRON IN PLACE OF 3/4" PI	BAR W/STD. PE IN MON.	CAP BOX			
C. Description of monument fo	r corner and accesso	ries established to perpetuate loc	ating the position of	the corner:	
5/8" X 24" IRON BAR W/9	STD. CAP IN MO	N. BOX			DAVID W.
NW COR. CONC. BLK. BLDO NE COR. HOUSE = \$30°E	G. = S65°E 207	.18'			DAVID W.
NW COR, PORCH = \$20°E	150.691			畫★	MOSTROM TROFESSIONAL
SW COR. CONC. FNDTN. OF	ENTRY GATE =	N77°E 145.40°			SURVEYOR No.
	ħ				32339
\ \(\lambda_{i,1}\) \(\lambda_{i}\)					DAVID W. MOSTROM PROFESSIONAL SURVEYOR NO. 32339 PROFESSIONAL SURVEYOR NO. 32339 PROFESSIONAL MILITARY PAGE
Signed by, . W.	W	DAVID W. MOSTROM	Date JUNE 11	. 1998	and Hill Hilling.