FEB 0 8 2000

SECTION

	LAND	D CORNER RECOR	DATION CERTIFIC	CATE			
For corners in	7 1141	18 vedamenteur of W	.ct 74, Mich. P.A. 1		2 29.	3	
St. Joseph	Located In:	Corner Code #	}	LIBER D	PAGE 17		
(County) Sturgis Twp. 1. Public Land Survey	<u>T8S</u> R_ TR_				STATE OF ST. JOSEI FILE	PH COUNTY	
0.5	TR_ TR_		_	7	JUN 1999	10:44:54 A	Ħ
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR		_		CYNTHIA L REGISTER	. JARRATT OF DEEDS	
				Registe	r of Deeds	Stamp & Fil	e Number
4. Lot No, Recor 5. Private Claims	ded Plat	•		A B C	DEF	GHI	J K· L
				2 6	_	3	- 2 1 -
ı, David W. Mostrom	in a field surrow on	5/4 40 99 4	hander to the state of	3			+
requirements of P.A. 74, Michiga conformance with regulations and	in P.A. of 1970, the come	er points mentioned in lines	1 and 2 shows were in	1 1 1	- 8 9 - 	10	11-12
United States Department of the lithat the corner points mentioned	nterior. Bureau of Land Ma	anagement or by a decree o	fa Court of I aw and for	6 18		15	1413
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court of	Law; established, re-esta	ablished, monumented,	7	1		
NOTE: Not more than 2 com		and maga, may be seen	and a d	8 19	20 21	22	23 24
on this certificate.	os, and the same wym	rand range, may be reco	iided	10 30	-29 	27	26 25
•				11		1-1-	1
				12 31	-3 ² 3 ³	34 -3	3536-
A. Description of original mor (M-5) NE Cor. Sec. 1	3 T8S, R10W	s and/or subsequent re	storation:	13			1
*1877 Survey in Bk A, Found +'d stone set b		979 Mostrom Sur		995 LCRC	in Bk 4,	Pg 175	
'1960's Road Commission		Fd. sh. pipe in Mo P. Pole = S43°W 4	on.box Se	et ½" bar o Mon. box		ched stor	ne
Pipe in Mon. box	P	P. Pole = N47°W	44.42' To	op/Center	of sa. p	lug on	
Cor. falls 41.2' North Fawn River Twp. Corr		Brace Pole = S53°	'E 52 . 15' ga *3.	as valve = /4" pipe i n	$N50^{\circ}E = 5$	8.45'	21
•			Pl	k in P. Po	le = N45	s°W 40.33	3'
B. Description of corner evidence	ence found and/or met	thod applied in restoring	or reestablishing corr	k in P.Po ner: @F-W	le = \$43 rdwv. =	°W 44.45 : South :	, ¹
Found ½" x 18" iron b	oar over notched	d stone in Mon. b	oox	Top fi	re hydra	nt = N30	°W 65.
Fawn River Twp. Cor. Top/Center of sq. plug Pk in P. Pole = \$43°V	g on gas valve =	(GLO = 40.92') = N50°E 58.45'	* Sl	hould be S	outh 41.	21	
Top fire hydrant = N3 Corner falls in € of L	0°W 65.1'	. 21 North	RATIFI	ED BY PEE	R GÉOIH	D.	
of Fawn River Road		: 3. NOLLII	IN ACC	CORDANCE	WITH P.A	. 345	
Set $5/8$ " x 20 " iron be over stone in Mon. bo			ON U <i>Klu</i>	CO REF	PRESENTA	9 <i>99</i> Ative	
C Description of manufact for							
C. Description of monument for (M-5). NE Cor. Sec. 1.	TRS POW	les established to perpe	tuate locating the pos		ner: Www.		
5/8" × 20" iron bar w N & W 2.0' high in N N & W 2.0' high in N	/std. cap over s E side of P. Po W side of P. Po	ole = N45°W 40.3 ole = S43°W 44.	× 37' 42' **	DAVID W. MOSTRON PROFESSIONA NO. 32339	Cyz*		LIBER
Center of sq. bolt on Center of top bolt on	gas valve = N50 fire hydrant = N	N30°W 65.10'	MINIMA	SURVEYOR No. 32339	BO'S WILLIAM		PAGE
\ \ \ \ .	. 1			MINIMUM ESSION	Miller.		-

David W. Mostrom

Surveyor's Michigan License No. 32339

May 20, 1999