Con s. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

M. R.

17 & 18

T. 40 Schoolcraft & Delta COUNTYS DESCRIPTION OF CORNER Township Corner for Sections 1, T40N, R18W and Section 6, T40N, R17W on 4th Correction Line. CORNER MONUMENT 1" Iron Pipe with 4" HrassCap. 7-11-61 DATE MOMMMENT PLACED AND WITHESSED S 150W 24" Hemlock (NBT)  $57\frac{1}{5}$  links WITHESSES TO CORNER. 9" Hemlock (Sl NBT) S 11°W links (NBT) S Ol°E 18" Y. Birch 40 links 40 - 17 AND

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed 3.00 chains West of & Corner on South side of Section 32, T41N, R17W as recorded in Field Notes. ( Corner is original corner set by Carl Christensen).

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

DATE January 31, 1962 Billy D. Buckler