SCHOOLCRAFT COUNTY PEER GROUP APPROVED

4 PAGE: 349

SURVEY & REMONUMENTATION

FEB 08 2001

DATE 10/10/00 TUS LAND CORNER RECORDATION CERTIFIC Filling Requirement of Act 74, Mich. P.A. 19	CATE 970 SECTION
For corners in	250 ION
Schoolcraft Located In: Corner Code #	DRCDC 45
1. Public Land Survey T 42NR 14W G3 Page 1 of	DBERG 1P DOLCRAFT CO.REGISTER LC 4/369
	1 LC 4/369 12/19/2000 Time 11:53:17
TR	
2. Property Controlling S T R	
in Section S T R 3. Miscellaneous S T R	
Property in Sec. S TR	Register of Deeds Stamp & File Numbe
4 Eat No Recorded Plat	
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L
_ · · ·	2 6 5 4 3 2 1
Thomas P. O'Brien, in a field survey on 10/31/00 to do hereby state that under	3
requirements of P.A. /4, Michigan P.A. of 19/0, the comer points mentioned in lines 4 and 2 above upro in	4 7 8 9 10 11 11
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	5 18 17 16 15 14 17
hat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
ecovered, found as expressed below:	8 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
	11 29 28 27 26 25
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
April 11, 1851 Algernon Merryweather, DS set Section Corner 3, Sugar 10 in N7OE 5 links Beech 6 in S4OW 15 links	4,9,10
Nov.22, 1975 Thomas P. O'Brien, PS "found 2" iron bar raised twith 21274 cap.	o surface with ½" iron bar
June 9, 1976 Herbert L. Fluharty "fd. ½" iron in centerline 4-	way intersection.
Description of corner evidence found and/or method applied in restoring or reestablishing corn	ner'
Oct.31, 2000 Thomas P. O'Brien recovered iron bar reset from e Reset with Schoolcraft County monument.	
mortality inortality.	•
. Description of monument for corner and accessories established to perpetuate locating the posi	ition of the corner
	at the conner.
Schoolcraft County monument stamped to identify.	
Schoolcraft County monument stamped to identify.	wise OF Morro.
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03'	THE OF MICHIES
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03' Gate Post S19°E 37.48'	THOMAS P.
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03' Gate Post S19°E 37.48' Power Pole S57°W 44.65'	O'BRIEN I
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03' Gate Post S19°E 37.48'	O'BRIEN =
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03' Gate Post S19°E 37.48'	O'BRIEN PROFESSIONAL S SURVEYOR NO. 21274
Schoolcraft County monument stamped to identify. Witnesses: 20" Twin Spruce N49°E 46.80' 24" Twin Spruce N72°E 81.03' Gate Post S19°E 37.48' Power Pole S57°W 44.65'	O'BRIEN I