CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established 1.85 chains (record distance) North of Section Corner 24-25, T43N, R15W.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR
Billy D. Buckler

Sechles DATE December 29, 1961