

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..43. NR..14..W

.S_c_h_o_o_l_c_r_a_f_t COUNTY

DESCRIPTION OF CORNER 1/4 corner between Section 12 and 13

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 9" Tamarack (1/4s NBT) N 72° E 31 1/2 Links

6" Tamarack (1/4s NBT) S 25° W 29 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was re-established midway and on line between two
section corners. No evidence of original corner.

Corner was placed and witnessed July 24, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 2/24/60