

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45-46N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 4-33

CORNER MONUMENT ½" iron pipe

DATE MONUMENT PLACED AND WITNESSED 9-9-70

WITNESSES TO CORNER..... 10" Cedar (¼S NBT) N30°W 10.9'



10" Tamarack (¼S NBT) N18°E 8.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by U.S. Dept. of Agriculture, while running the boundary of the Seney Wildlife Refuge.
Found iron pipe in place with a 9" cedar, bearing south 3.8', marked as a witness.
Found no evidence of the original Tamarack witnesses.

Cor. lies in a wet cedar swamp.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 9-22-70
REGISTERED LAND SURVEYOR