## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 46 NR 14 W

|             |   |        |              | _2      | p o o j | Loraft    | COUNT    | Y |
|-------------|---|--------|--------------|---------|---------|-----------|----------|---|
| DESCRIPTION | OF CORNER 1/4 Corner between Sections 3 and 4 |        |              |         |         |           |          |   |
| DESCRIPTION | OF  | CORNER | MONUMENT     | l" Pipe | with 4  | Brass Cap |          |   |
| WITNESSES   | то  | CORNER | 8" Red Pine  | (1/4s   | NBT)    | N 200 B   | 19 Links |   |
|             |   |        | 18" Red Pine | (1/48   | nbl) -  | _N_460_M_ | 86 Links |   |
|             |   |        |              | <b></b> |         |           |          |   |
|             |   |        | ·            |         |         |           |          |   |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway between two Section Corners. No evidence of original corner. Corner lies on edge of high ground and in an old dugout.

Gorner was placed and witnessed April 28, 1960.

SURVEYORS SEAL

SIGNED SURVEYOR Billy D. Buckler

DATE 5/18/60