

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 46 N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 23-26

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-11-61

WITNESSES TO CORNER..... 4" Soft Maple (1/2 S NBT) N 70°W 19 links



4" Cedar " " S 20°E 14 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at old wood post set by unknown surveyor. Found old blazes in line to West. No evidence of Tamarack B.T.'s.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 13, 1962  
REGISTERED LAND SURVEYOR  
Billy D. Buckler