

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR. 13. W. . .

----- Schoolcraft Co. ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 16, 21 -----

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 1/4" brass cap -----

WITNESSES TO CORNER 18" W. Pine S 82 1/2° W 70 links -----
Marked 1/4S NBT

15" W. Pine N 6° E 150 links -----
Marked 1/4S NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner, Midway and on line between two Section Corners.
No evidence of Original Corner
1/4 Corner lies 79 links West of Centerline of M-77 and 25 links South of trail road to West.

Corner re-established and witnessed October 30, 1956.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 11/8/56