9881 5 1993

C. WINGSHION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 DEC - 6 MIN: 00

periored or males They en the whole SHIMANGER, SHILLA MOIT

For corners in REMONUMENTATION Shiawassee 'Located In: Corner Code ≠≠ ЬN R. 1. Public Land Survey WHATE OF MICHAEL _ R _ т R R R R TO SU. 12016 R _ T **Property Controlling** T _ T in Section S S T Miscellaneous Property in Sec. ___ , Recorded Plat Private Claims _

Register of Deeds Stamp & File Number

, 19 <u>9</u>3 Norman C. Caldwell in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1-11 1/4 cor., Sec. 25 & 36, 16N-R1E

Wood post placed by J. Wampler, 1826, N45°E 21 lks. (13.86°) 11" W. Oak S59°W 16 lks. (10.56°) 11" W. Oak

Survey by E. Mason, Co. Surveyor, June 1869, recorded in S.C.R. Book A, pg. 27, Monument Not Given N76°W 92.25 lks. (60.88') 18" W Oak \$36 1/2°E 105.75 lks. (69.80') 14" S. Oak

Surveys by W. L. Paddison, 1976 & 1978, recorded in L. 2, pg. 397 & L. 3, pg. 25 of Surveys. Bolt head CL Fenner Road in line w/fence to the East

Unrecorded survey by A. F. Miller, 1981 Fnd. PK Nail N & T Tele. Pole

N85°W 32.7' N50°E 65.13' N & T Power Pole S84°E 32.95 N & T 36" Oak

Surveys by J. A. Sellek, 1980 & 1984, recorded in L. 2, pg. 228 of Corners, & L. 4, pgs. 105 & 202 & 203 of Surveys, Bolt w/PK Nail per L. 3, pg. 25 of Surveys \$70°E 32.95' N & T 40" Oak \$35°W 56.97' N & T 12" Hickory West 32.32' N & T 19" Oak

٠:

Surveys by L. A. Bryan, **1986 & 1987**, recorded in L. 5, pgs. 516 - 519, 650 - 652 ¢677 of Surveys Fnd. R.R. Spike CL Fenner Road on E-W fence lines per L. 2, Fnd. N & W S. side 40" Oak

pg. 228 \$80°E 33.051 ^35°W 56.961 ~2.001 Set N & T SE side 16" Hickory Set N & T S. side 14" Oak

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1/4 cor., Sec. 25 & 36, T6N-R1E

Fnd. R.R. Spike in CL Fenner Road per L. 2, pg. 228 of Corners, and L. 2, pg. 397, L. 3, pg. 25, L. 4 pgs. 105 & 202 -203 and L. 5, pgs. 516 - 519, 650 - 652 & 676 - 677 of Surveys. Replaced with a standard 20" Harrison marker in mon. box as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-11 1/4 cor., Sec. 25 & 36, T6N-R1E

Fnd. R.R. Spike in CL Fenner Road per L. 2, pg. 228 of Corners, and L. 2, pg. 397, L. 3, pg. 25, L. 4 pgs. 105 & 202 - 203 and L. 5, pgs. 516 - 519, 650 - 652 & 676 - 677 of Surveys. Replaced with a standard 20" Harrison marker in mon. box, as approved by the Shiawassee County Peer Review Group and is accepted as the best available evidence of the position of the original corner. \$70°E 31.05' Set N & T #12018 in S. face 50" Oak (R - tree) \$35°W 57.21' Set N & T #12018 in E. face 14" Hickory (R - tree) West 32.09' N68°W 32.60' Set N & T #12018 in N. face 14" Oak (R Fnd. N & T in S. face Tele. Pole (R)

Signed by

Z DEC 93

Surveyor's Michigan License No.

12018

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975