SEP 2 9 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

RECORDED

94 SEP -6 ANTH: 05

For corners in			uirement of Act 74, Mich. P.A. 1970	VEGIOTEV OF DEFINO
Shiawassee (County)		Located In:	Corner Code ##	Shayer Shuddan SHIAVASSEE COUNTY, MICH.
1. Pub	olic Land Survey	T 6N R 4E T R T R		
2. Pro	perty Controlling	S T R		
in S	Section	S T R		
3. Mis	cellaneous	S R		egister of Deeds Stamp & File Number
Pro	perty in Sec.	S R		
				— ABCDEFGHIJKLM
5. Priv	ate Claims			- ,
				³
				4 - 7 - 4 8 9 - 10 - 11 - 12 - 12 - 12 - 12 - 12 - 12
1, Norman C. Caldwell , in a field survey on			<u>July</u> , 19 <u>94</u> ,	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of			P.A. of 1970, the corner points mentioned	6 18 17 16 15 14 13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of Li			s and rules therefore as required in the	7
current manual of survey instructions of the United States Depar Management or by a decree of a Court of Law and/or that the corne			orner points mentioned in lines 3. 4 and 5	8 10 20 31 23 32
			ard of Land Surveyors or by a Decree of a	20 21 22 20 21
Court of Law; established, re-established, monumented, re-m			re-monumented, recovered, found as	9
expressed below:				10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and			n and range, may be recorded	11
NOTE:	on this certificate		if and failige, may be recorded	12 32 33 34 35 36
	On this Certificati	c.		13
A. De	scription of origina	I monument and accessories	and/or subsequent restoration:	
L-13	Std. 1/4 Cor., Se	73	₩	
	S31°W 13 lks. (8	by J. Mullett, 1848— 3.58') 6" B. Ash 23.76') 9" Butternut	Surveys by M.L. Vanraemdonck, 197 L. 2, pg. 575-576 & Pg. 624 of su Set PK Nail North 40.70' Set N & I 12" Map	urveys.
		ins, Co. Surveyor,	\$10°W 33.70' Set N & T Tele. Po	·
		ed in County Surveyors	S05°W 48.26' Set N & T 10" Pop North 19.80' Set N & T Top C.8	
	records BK A, pg. Mon. & Refs. Not		Survey by J.S. Fokens, 1983 reco	
	Field Bk. 12, pg.	uine, 1966 recorded in . 136	of surveys per L. 2, pg. 575-576	& pg. 624
	Mon. Not Given	Vallay Steel Book	Survey by N.C. Caldwell, 1989 rec pg. 609 of corners and L. 5, pg.	
	North 40.7' 12'	Yellow Steel Post 'Maple	Fnd. PK Nail, replaced w/bar & c	
	North 19.8' Cer	nt. 4' sq. conc. C.B.	North 40.70' N & T 12" Maple	
	SW 36.5' Cer	nt. 4' sq. conc. C.B.	\$10°W 33.70' N & T NE fc. Powel North 19.8' Cent. 4' sq. conc	
	Survey by F.J. Mr	cCombs, C.P. Co. 1972	\$45°W 36.5' Cent. 4' sq. conc	
		pg. 44 of corners	2.5 2 2 2 2 2 3 2 3 3 3 3 3 3 3 3 3 3 3 3	APPROVED
	Fnd. R.R. Spike	in CL Black top road		MELUARD
	South 44.30' 4' \$20°E 53.00' 8'			County Remonumentation
	250 E 33.00. Q.	VAII.		COCILIA LIGHTORIGINGINGING

County Remonumentation Peer Review Group

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 8/16/94 MLV

L-13 Std. 1/4 Cor., Sec. 36, T6N-R4E

N01°W 41.68' 8" Maple

Fnd. rerod w/smashed cap in CL asphalt road per records (above), replaced w/a std. 20" Harrison marker and mon. box as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Std. 1/4 Cor., Sec. 36, T6N-R4E

Surveyor's Michigan License No.

Fnd. rerod w/smashed cap in CL asphalt road per records (above), replaced w/a std. 20" Harrison marker and mon. box as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the best available evidence of the position of the original corner. \$10°W 33.69' Fnd. N & T NE fc. Power Pole (R)
North 19.88' Cent. 4' sq. conc. C.B. (R)
\$60°W 36.49' Cent. 4' sq. conc. C.B. (R)
North 33.00' Fnd. 1/2" rerod w/cap #11192 (R)

Signed by 12018

Date

CALDWELL POFESSIONAL MOPESSION MANAGER SION AND

LAND SURVEYORS, JAN, 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983