SURVEY & REMONUMENTATION

SEP 2 9 1994

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

R	EC	OF	ÌΠ	F

94 SEP -6 ATTH: 06

REGISTER OF DEEDS

SHIAWASSEE COUNTY, MICH.

Register of Deeds Stamp & File Number

Shiawassee (County) Located In: Corner Code ## T 6N R 3E 1. Public Land Survey T ____ R _ T R T _____ R _ ____ T ____ R _ 2. Property Controlling ___ T ____ R _ in Section ___ T ____ R _ Miscellaneous **ÅPPROVED** Property in Sec.

____ , Recorded Plat _

5. Private Claims ___

County Remonumentation

Peer Review Group MLV. 8/16/94

Norman C. Caldwell July 19 94 ., in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration:

M-13 TWD. COT., TEN-RE & 4W & TEN-RE & 4W

Wood post placed by J. Mullett, 1823 \$39°E 29 lks. (19.14') 14" W. Oak N63°W 57 lks. (37.62') 14" W. Oak

Survey by E. Mason, Jan. 1882, recorded in County surveyors records 1874-1888. S.C.R. Mon. & Refs. Not Given

Survey by E. Mason, June 1883, recorded in County Surveyors records 1879-1900 pgs. 104-105, S.C.R. Mon. Not Given N60 1/4°E 55 1/2 lks. (36.63') 15" Y. Oak S25°W 84 2/3 lks. (55.88') 15" W. Oak S42 1/2°W 62 lks. (40.92') 10" S. Maple

Survey by M.L. Vanraemdonck, 1978, recorded in t. 3, pg.89-90 of surveys fnd. hub & 1" sq. rod 2' deep, raised w/rerod

East 26.60' \$10°W 78.80' R.R. tie cor. post \$10°W 78.80' 2" rd. fnc. cor \$10°E 80.50' N. fc. 30° Oak

Surveys by M.L. Venraemdonck, 1984 (Unrecorded) and 1987, recorded in £. 5, pg. 35 of surveys. Fnd. 1/2" rerod (top bent)

10

11

12

13

Hast 26.80' W. fc. R/R/ tie fnc. post N45°W 28.70' N & W E. fc. 8" Elm N30°W 31.85' N & W E. fc. 8" ELm S20°E 80.90' N & W W. fc. 24" Oak

Survey by S.J. Szyszkoski, Dec. 1988, Recorded in L. 2, pg. 577 of corners. Fnd. & accepted 1/2" rerod in CL Geeck Road at W'ly Projection of 15-20 yr. old wire fnc. line to East.

'880°W 18.98' Set N & T #11192 S. ic. 14' ELm

N45°W 31.82' Set N & T #11192 E. fc. 10" Elm

East 27.10' Set N & T #11192 S. fc. R/R tie anchor post

S15°E 80.31' Fnd. N & T W. fc. 30" Oak

Survey by N. C. Caldwell, Oct. 1990, recorded in L. 5, pg. 815-816 of Surveys.
Fnd. 1/2" rerod & placed #12018 cap
See L. 2, pg. 577 for refs.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: В.

M - 13Twp. cor., T6N-R3 & 4W, T5N-R3 & 4W

Fnd. 1/2" rerod. When excavating to replace 1/2" rerod w/a std. 20" Harrison marker, fnd a 1" sq. rod South 0.23' held this position as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the best available evidence of the position of the original corner.

Measurements along the range line agree with E. Mason Survey of 1883.

Description of monument for corner and accessories established to perpetuate locating the population of the corner:

Twp. cor., T6N-R3 & 4W, T5N-R3 & 4W C. STATE OF MICH

Fnd. 1/2" rerod. When excavating to replace 1/2" rerod w/a std. 20". Harrison marker, fnd a 1" sq. rod South 0.23' held this position as approved by the Shiawassee County Remon. Peer Review Group and is accepted as the best available evidence of the position of the original corner.

Fnd. N & T #11192 S. fc. R/R tie anchor post (R) Fnd. N & T #11192 S. fc. 14" Elm (R) Fnd. N & T #11192 E. fc. 10" Elm (R) Fnd. N & C #12018 W. fc. 30" Oak (R) East 26.76' N65°W 19.33' N30°W 32.04'

S15°E 80_731

Geldull Signed by

_ Date _

Surveyor's Michigan License No. _

1201 8

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

NORMAN C. CALDWELL PROFESSIONAL SURVEYOR No. 12018 Coregao M