

July, 1963 M.S.H.D. witness card Cor. A-2, T11N-R11E
by H. G. McManus, Survey Chief.

3/4" Iron.
West 33.65' 18" Maple.
N60°W 37.31' 20" Maple.
East 26.74' fence post.

Aug. 23, 1974

Survey by David T. Rowe, Land Surveyor #11192, Liber 443-Page 850.

1/2" Re-rod.
West 33.65' RLS tag 11192 in 20" Maple.
N60°W 37.31' RLS tag 11192 in 24" Maple.

April 20, 1979

Survey by Charles S. Getz, Land Surveyor #25843, Liber 304-Pages 1069 & 1070.

Fnd. 1/2" Iron.
West 33.65' 18" Maple.
N60°W 37.31' 20" Maple.
N30°W 61.30' nail 12" Pear.

Dec. 1, 1983

Survey by Richard R. Boldt, Land Surveyor #28405, Liber 539-Pages 851 & 852.

Fnd. 1/2" Iron (common to W 1/4 Cor. Sec. 6, T11N-R11E)
S15°E 129.94' set spike w/cap in 22" Maple.
West 33.50' set spike in blaze on S. face 24" Maple.
N75°W 37.16' set spike in blaze on S. face 24" Maple.

Dec. 22, 1983

L.C.R.C. form filed by Richard R. Boldt, Land Surveyor #28405 Page 46, Dayton Twp.

Same object & accessories as Liber 539-Pages 851 & 852.

Sept. 13, 1995

Survey by Jonathan M. Field, Land Surveyor #37276, Liber 683-Pages 22, 23 & 24

Fnd. 1/2" rod.
West 32.14' set nail w/tag #37276 in E. face 24" Maple.
N70°W 36.86' set nail w/tag #37276 in SE face 32" Maple.
N20°W 108.01' set nail w/tag #37276 in E. face mailbox post.
N60°E 24.40' set nail w/tag #37276 in N. face 8" Elm.

