ifg ≥ 8 **2000**

COTION

1994 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

For corners in NOVESTA	TOWNSHIP	ement of Act 74, Mich. F.A.	
TUSCOLA	Located In:	Corner Code ##	STEEL VED
1. Public Land Survey	T R T R		FOR REC PAGE # 20 9 PH 2: A COUNT A COUNT
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Ro	ecorded Plat		A B C D E F G H 1 J K L M 2 6 5 4 3 2 2 1 3 4 7 8 9 10 11 12
do hereby certify that under reg in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law; established, reexpressed below: NOTE: Not more than 4 co	urrements of P.A. 74, witchigam A conformance with regulations are tetions of the United States Depart a Court of I.aw and/or that the corn	19 , 19 94 . of 1970, the corner points mentione and rules therefore as required in the interior. Bureau of Lan er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found and range, may be recorded	5 8 19 20 21 22 23 24 4
on this certificate.		od/or subsequent restoration:	13

Description of original monument and accessories and/or sub

1834 (Gov't. Land Office Notes) Harvey Parke, D.S. Set qr. Sec. post- Sugar 20 S49W 20; Hemlock

1889 (Resurvey of Evergreen Twp., T13N-R12E, Sanilac County)F.F. Rogers, Surveyor -Set Vitrified Stone 'corner' 3 inches in diameter and 3 feet in the Earth- gives no accessories.

1895 (County Surveyor's Record pages 140 and 141, Sanilac County) M.E. Ward, Surveyor -shows "crock" previously set by Rogers- gives no accessories.

1972 (Survey -Liber 2 of Surveys, pages 130 and 131, Sanilac County) David T. Rowe, P.S. 11192 -Set "T" Iron- West 84.94' RLS tag in PP; N40°W, 45.39' Nail & Cap in TP; S15°E, 99.30' RLS Tag in 8" tree

B. Description of corner evidence found and/or method applied in restoring or reestablishing cornér: Found "T" Iron and 30" of 3" diameter "Vitrified Stone" --Vitrified Stone in two sections-- top section had upper 6"+/- broken off, bottom section (1 ft.) had cross cast in top.

Accepted found objects as marking original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Removed found objects and replaced with Standard Tuscola County Concrete Monument with 2" Brass Cap stamped M8 T13N/R11E

N829E,40.40' -T.C. Re-mon. tag in South face of 6" Twin Elm S40°E,50.99' -T.C. Re-mon. tag in Southwest face of 7" Locust S24°W,46.57' -T.C. Re-mon. tag in Northwest face of 5" Ash

West, 85.28' -T.C. Re-mon. tag in North face of Power Pole (also found tag 11192 in East face)

HONEL ROY EMERY LAND -NO: Date APPROVED 24593 Surveyor's Michigan License No. 24593. -10-94 Professionen

Jimst

MIC

1975 (Land Corner Recordation Certificate, Sanilac County) James A. Beck, P.S. 21559 -Found bits of iron & decayed wood at 30" deep, perpetuated with 2' x 1/2" iron rod- S70 E, 71.77' nail & Tag in root 18" Maple; S45 E 39.21' spike in center 30" stump; S50 W 74.59' nail & tag in PP; N55 W 63.24' nail & tag in Tel. Pole
1975 (Survey, Liber 3, pages 322 and 323, Sanilac County) James A. Beck, P.S. 21559 --corner marker

and accessories same as Land Corner Recordation Certificate.

SURVEY & ONUMENTATION

TEC 2 8 2000 -

PECTION

