

MAR 02 1999

, Recorded Plat

4. Lot No. 5. Private Claims

on this certificate.

## 1998 REMONUMENTATION PROGRAM

RECEIVED FOR RECORD LIBER NO.\_\_ \_PAGE NO. THE NO #62 Elmwood Two.

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

98 DEC 18 AN 10: 06

For corners in SECMOON OWNSHIP Located In: Corner Code # TUSCOLA COUNTY REGISTER OF DEEDS

TUSCOLA 14N<sub>R</sub> 10E 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

LIONEL ROY EMERY  $\underline{\text{OCT. }}$  19  $\underline{\underline{98}}$  do hereby state that under in a field survey on \_ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or

that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded

4	Δ	D .	ر ا	<u> </u>	Ŀ	r	اتتا	н	Τ.	J	ĸ	Ŀ.	١
1			]		П					T	T	Τ	
2	├	6—	-	5	$\vdash$	<u>4 —</u>	₩	å	ــــ	ģ	₩	i-	_
3	<u> </u>	<u> </u>	ŀ	<del> </del>	┞	L	-		<u> </u>	_	_	_	_
4		<u> </u>	-	ė —	-	ا 9—	1	ا ا0	<u> </u> -	 ! <b>1</b> —	<u> </u> -	[ [2—	
5	<u> </u>	-	_			L			-	<u> </u>	-	-	_
6	<del> </del>	<del>9</del>	-1	7	1	6 1	-1	<u>;</u> 5—	1-1	 	<del>  1</del>	! .3	_
7		<del>                                     </del>			ļ		<u> </u>	<u> </u>	ļ	<u> </u>	<b> </b>	<u> </u>	
84	1	ا وا	2	0	2	  1	2	2	2	 :3—	<u> </u> _2	4	
9	_		L						<u> </u>		_	L	
10	L:	0	2	9	2	8	2	  7—	2	6	2	 :5—	
11											<u> </u>	L.	
- 1	3	 1—	3	 2—	3	3	з	4	з	[ 5—	<u>L</u> 3	6	
13										Ĺ	L	Ľ	ļ

A. Description of original monument and accessories and/or subsequent restoration;

1835 GLO NOTES (PG. 327): HERVEY PARKE, DEP. SUR. SET QR. SEC. POST; CEDAR 12 S24W 35; HEMLOCK 15 N5W 23 1895 COUNTY SURVEYOR'S RECORD (PAGES 260 AND 261) BY: EDWARD L. TESKEY, COUNTY SURVEYOR'S SURVEY OF SECTION 24, T14N-R9E; STAKÈ-ESTABLISHED AT PROPORTIONATE DISTANCE BETWEEN SECTION CORNERS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

ALL EVIDENCE OF CORNER MARKING IS LOST EXCEPT FOR FIELD DIVISION LINE EAST AND WEST REESTABLISHED CORNER POSITION BY SINGLE PROPORTION METHOD, THIS POSITION IS IN AGREEMENT WITH FIELD DIVISION (NO FENCES) CULTIVATION LINES ONLY.

ACCEPTED SINGLE PROPORTION POSITION AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF ORIGINAL GOVERNMENT CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. SET STANDARD TUSCOLA COUNTY CONCRETE MONUMENT WITH 2 IN. DIA. BRASS CAP STAMPED M8 T14N R9E

-PLACED MONUMENT BOX OVER MONUMENT.

N28°E, 31.25 FT. SET 1/2" REROD IN GRAVEL SHOULDER

SET T.C. REMON TAG IN NORTH FACE OF RAILROAD TIE POST SET 5/8" RE-ROD IN GRAVEL SHOULDER S88'E, 43.07 FT.

S35°E, 30.14 FT.

S85°W, 49.89 FT. SET T.C. REMON TAG IN SOUTH FACE OF POWER POLE

WEST, 33.44 FT. SET T.C. REMON TAG IN NORTH FACE OF WOOD POST

NOTE: THIS CORNER IS COMMON WITH CORNER M 8 T14N R9E (COLUMBIA TOWNSHIP)

Signed by

24593 Surveyor's Michigan License No.

DECEMBER /8, 1998

APPROVED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

LIONE

EMER

AND NO.

## SURVEY & REMONUMENTATION

MAR 02 1999

## SECTION

