expressed below:

1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECLIVED FOR RECORD
LIDER 110. PAGE NO.
THE R. #42
1-111/07/

LIDER IID. PAGE NO.
THE R #42
ELMWOOD TOWNSHI
97 OCT -9 PH 1: 07

tamp & File Number

For corners in: ELMV	OOD TWP.		97 001 -
TUSCOLA (County)	Located I	n: Corner	Code # Oprogra
Public Land Survey	T <u>14N</u> F T F T F	}	TUSCOL REGISTE
Property Controlling in Section	S T F		Posistan of Dondo C
Miscellaneous Property in Sec.	S T F S T F	· 	Register of Deeds S
4. Lot No,	Recorded Plat		1 A B C D E

JULY 25 1, <u>JONATHAN M. FIELD</u>, in a field survey on <u>JULY 25</u> 19 <u>97</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the <u>JONATHAN M. FIELD</u> current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A B	c b	E F (⊋ н :	IJΚ	LM
-6-	-5	4	3	- 2	.]
 					
7	8	9	10	-11	12
 			1	-	
18	17	16.	15	14	13
					
19.	20	21	- 22	23	24
		<u>:</u>	<u></u>		
30	29	28	27	26	25
	 -				
31	32	33	34	35	36
	7 18 19	7 8 17 19 20 30 29	6 5 4 7 8 9 18 17 16 19 20 21 30 29 28	6 5 4 3 7 8 9 10 18 17 16 15 19 20 21 22 30 29 28 27	6 5 4 3 2 7 8 9 10 11 18 17 16 15 14 19 20 21 22 23 30 29 28 27 26

Description of original monument and accessories and/or subsequent restoration:

1835 GLO; PARKE, D.S.; SET POST; BEECH 16 N49W 38LKS., BEECH 16 N69E 57 1/2LKS.

1891 FELTON, C.S.; SURVEY OF SEC. 34; SET FROM MEAS. (NO OBJECT STATED); SUGAR 4 N30 3/4E 59LKS., ELM 10 S68 1/2W 116LKS.

S68 1/2W 116LKS. $_{\rm T-IRON}$ 1976 TOMMER; LCRC PG.14; FND. NOTHING; SET ON LINE & EQUIDISTANT FROM G-13 TO H-13 BASED ON 1891 RESURVEY; WEST 17.54' T-IRON, S45E 65.05' FACE OF P.POLE, \$70W 69.75' TOP OF TEL. RISER

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1997 ROWE; FIELD, P.S.#37276; FND. T-IRON; RECOVERED 3 PREVIOUS WITNESSES WHICH INDICATE THAT FND. T-IRON IS IN SAME POSITION AS 1976 LCRC CITED IN SECTION A ABOVE

ACCEPTED FND. T-IRON AS BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER POSITION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

REPLACED FND. T-IRON W/ STD. REMON. MONUMENT STAMPED I 13 T14N R10E IN MON. BOX

WEST, 17.62' FND, T-IRON APPARENT CORNER I-1 T13N-R10E \$35°E, 65.12' FND. NAIL W/TAG #11192 IN SW FACE P.POLE

37276

S64°W, 70.13' TOP CENTER OF PHONE RISER

N60°W, 35.71' SET 1/2" ROD W/CAP #37276 S50°W, 43.00' SET 1/2" ROD W/CAP #37276

N38°E, 24.97' SET 1/2" ROD W/CAP #37276

JONATHAN **PROFESSIONAL** SURVEYOR 37276

OF MICH

Signed by

UPROVED BY MICHIGAN STATE !

APPROVED

REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

SUNVEY & REMONUMENTATIO!

Surveyor's Michigan License No.

NOV:2 6 1997

COMMISSION -

. 9

