FILED

JAN 1 4 1998

SECTION

VAN BUREN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DEC 16 12 00-PM '97

For corners in Located in: Corner ID # Mark a Smith VAN BUREN COUNTY GENEVA TWP. NE COR. SEC 24 T1S,R16W 1. Public Land Survey T 15 R 16W 2. Property Controlling R Liber 5 Page 44 in Section R 3. Miscellaneous P Property in Sec.

Register of Deeds Stamp & File Number

Lot No_ _,Recorded Plat 5. Private Claims

I, Alan Bartlett in a field survey on November 25 1997 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B C D E F G H 1 Α J KLM 20 22 24 27 26 25

(PLEASE SEE BACK OF PAGE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" IRON PIPE IN MONUMENT BOX 11' NORTH OF CENTER LINE OF EAV ROAD VERIFIED CORNER LOCATION USING EXISTING WITNESSES. THIS GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS NOVEMBER 19 1997.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 21/2" DIAMETER HARRISON MONUMENT IN MONUMENT BOX 11' NORTH OF CENTER LINE OF EAV ROAD

WITNESSES 47 34

N60°E P.K. NAIL IN WEST SIDE OF 5' POLE N62°E CL OF TELEPHONE RISER BOX 46.72 CL OF TELEPHONE RISER BOX S30°E 79.67 S42°W 67.16 CL OF TELEPHONE RISER BOX N20°W 73.27 DBL HEADED NAIL IN W. SIDE OF P.P. SOUTH 27.06 A-7 SW CORNER OF SEC 18 T1S, R15W

CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

Ratilied by Peer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor

12/16/97



Surveyor's

LIBER 5 PAGE

T1S,R16W M-7

GLO BROOKFIELD 1827

NORTH ON EAST BOUNDARY OF SECTION 24 80.00 SET COR. POST TO SEC 1 3 & 24

10/2/90 JOHN C. HUNT RLS#23513 LCRC LIBER 3 PAGE 172

FOUND 1" IRON PIPE IN CENTERLINE OF COUNTY ROAD 681 N&S CENTERLINE OF COUNTY ROAD 384 IS 12' SOUTH

WITNESSES

	WITNESSES	
SOUTH 27.06'	FOUND 1" PIPE	FOR N.W. CORNER OF SECTION 19 T1S, R15W
N20° W	73.20'	FND NAIL IN WLY FACE OF POLE
N50° E	47.15'	FND NAIL IN SLY FACE OF POLE
S40° W	67.30'	C/L OF TEL. CABLE BOX
S35° E	79.50'	C/L OF TEL. CABLE BOX

4/28/93 DONALD GILCHRIST RLS# 13583

FOUND 3/4" PIPE (BENT)

WITNESSES

POWER POLE	N30° W	73,15'
CABLE RISER	N45° E	46.55
CABLE RISER		79.52'
CABLE RISER		67.20'

11/17/1997

RLS# 35988 LANDMARK TECH. ALAN BARTLETT FOUND 3/4" IRON PIPE IN MONUMENT BOX 11' NORTH OF CENTER LINE OF EAW ROAD

WI	TNESSES						
N60°E 47.34'			EST SIE				
N62°E 46.72'							
S30°E 79.67'	и	**	ti	59			
S42°W 67.16'	tt	11	**	"			
N20°W 73.27'	DBL	DBL HEADED NAIL IN W.SIDE P.P.					
SOUTH 27 06'	A-7 SW CORNER OF SECTION 18						