JAN 1 7 1996

e./2 Cochina	SION LAND CORNE	R RECORDATION CERTIF	ICATE	
For corners in Waverly Townsh Van Buren	nip Filing Require Located In:	ement of Act 74, Mich. P.A. Corner Code #	. 1970	FILED
Public Land Survey	T <u>2S.</u> R <u>14W.</u> T R T R T R		Dec 29	8 55 AH '
 Property Controlling in Section Miscellaneous Property in Section 	S T R S T R S T R S T R		Register of Deeds Stamp	VAN BUREN CO. POINTER OF DEED!
4. Lot No, Rec			A B C D E F	G H I J K
do hereby certify that under requir in lines 1 and 2 above were in commanual of survey instructions of Management or by a decree of a 5 above were in conformance with Decree of a Court of Law; establis as expressed below: NOTE: Not more than 4 corner on this certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate. A. Description of original mediates are will be a corner on the certificate.	n a field survey on	Der 5 , 19 95 A. of 1970, the corner points mention rules therefore as required in the current of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and of Professional Surveyors or lated, re-monumented, recovered, for trange, may be recorded and/or subsequent restoration: 1974 - W.Q. Smith, C.S. Meas. from NE cocor. Sec 30 Almer 2657.81′ to SE cord.	oned frent 7 16 16 16 17 16 16 16 16 16 16 16 16 16 16 16 16 16	-10 -11
Found 1/2" iron in monumer	dence found and/or method at box measured North 26 wp.•½" iron was approve	d applied in restoring or reesta	also measured North 17.12' to	
· Iva			Ratified by Peer Group in accordance with P.A. 345 of 1 Van Buren County Surveyor	
Found 1/2" iron is ac reestablishment of Van Buren County and cemented in pl "PK" Nail & Tab in "PK" Nail & Tab in "PK" Nail & Tab in	ccepted as a careful and fathe position of the original Remonumentation brass ace, Accessories: N.E. side utility pole N. South side utility pole N. West side utility pole S. West side utility pole S	aithful al corner. Placed cap over ½" iron 55° W., 61.14' 60° E. 80.14' 45° F. 118.39' 35° W. 104.73'	ALLEN H. McMACHEN PROFESSIONAL SURVEYOR No. 16935 POFES SIONAL SURVEYOR 172 27 27 27 27 27 27 27 27 27 27 27 27 2	
Surveyor's Michigan License	No.	16935 FORM APPI	ROVED BY MICHIGAN STATE BOARD OF PROFESSIONA	L SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 199

Liber 4 Page 357