FIL	ED

Van	BO!	tv	Remonumentation	Program(V	2 47	PM '35
Van		ty	Remonumentation	Program(V	2 4	7

LAND CORNER RECORDATION CERTIFICATE				
Filing Requirement of Act 74, Mich. P.A. 1970	Δ4.	12	<b>C</b>	.71.

For comers in Arl ington		Center of Section 22	Y//ark COMIXA	7
Van Buren (County)	Located In:	Corner Code #	en/Control for Every	ξ
1. Public Land Survey	Ť <u> </u>	₹ <u>15₩ H8</u> ₹		0101 10SURVEN
Property Controlling     In Section     Miscellaneous     Property in Sec.	S TF S TF S TF		Liber 4 PAGE 483 Register of Deeds Stamp & File Nur	12/20
4. Lot No Recon	ded Plat			14

Gary C. Billow, in a field survey on 5/28, 19 93 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

5. Private Claims

A. Description of original monument and accessories and/or subsequent restoration:

Post not established by original government survey. Found no records of corner ever being established.

Ratified by Peer Group in accordance with P.A. 345 of 1930
Van Buren County Surveyor

Date 12/20/96 D. M. S.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:
Found 1-1/2" Well Point at the intersection of old downed fences projecting 1.5' above ground. Well Point is 2' North and 5' East of the calculated 1/4 line intersection.
Accepted Well Point as the corner.

THIS GOVERNMENT MONUMENT WAS RESTORED WITH THE APPOVAL OF THE VAN BUREN COUNTY REMONUMENTAION PEER GROUP OF SURVEYORS AT A MEETING HELD OCTOBER 9, 1996, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced Well Point with Harrison Monument on 12/19/96

•		
S73°E	6.64',	Nail & Tag in 10" Maple
S2°W	25.89'	Nail & Tag in 8" Maple
N66°W	29.34'	Nail & Tag in 8" Beech
N1 5°W	31.997	Nail & Tag in 15" Beech

Signed by Surveyor's Michigan License No. 26453

GARY C.
BILOW
PROFESSIONAL
SURVEYOR
No.
26453

Date December 19,1996

PAGE 12