	<u> </u>				
	WHIVEY				
62	A COLUMN SALES MANAGEMENT AND AND ADDRESS OF THE PARTY OF				
SEMO	MONEGAL				

MAY 1 6 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DEC 17 39 PM 196

Mark a Smith	•
CEAN BUREN CO	

For corners in	,	Filing Requirement of Act 74, Mich			
Van Buren Co., Antwerp Twp.		Located In:	Corner Code #		
1. Public Land Survey 5,ಲ , Cor , Sec.	27	T.3 S. R.13 W T R T R T R	G-11		
2. Property Controlling in Section	S	T R T R			
3. Miscellaneous Property in Sec.	S	T R T R			

12/17 0101 10SURVEY LIBER 4 PAGE 448 Register of Deeds Stamp & File Sumber

4. Lot No	Recorded Plat
5. Private Claims	

I, _James E. Boynton in a field survey on . June 26 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed

3 5 9 11

2

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner position established in 1829 by William Brookfield, D.S. Stone found and used in 1900 by W. H. Goss, C.S., by W. V. Ackley C.S. in 1909 and by T. A. Smith C.S. in 1923. A 1\2" pipe was found and used in many surveys from 1971 by W. Q. Smith, C. S. through 1976 by J. C. Hunt, P.S. Railroad spike found and used in 1994 by D. R. Gilchrist, C.S.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dug under the railroad spike and found a 1\2" pipe over a pointed stone as described by T. A. Smith in 1923. Accepted this stone as the best available evidence of the original corner position and set standard marker in place.

The standard marker is 2.10' South and 2.00' West of the railroad spike.

Ratified by Peer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor


Date 12/17/96 D. B.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard marker set in place of stone as directed by the Peer Group regular meeting on June 5. 1996.

24" Maple N.30°E. 56.37' to nail 30" Maple S.88°E. 24.20' to nail 18" Hickory \$.20°E. 57.90' to nail Power pole S.70°W. 53.74' to nail

The 30" Maple was used as a reference to the corner almost continuously since 1900 to present.



Signed by _	James	٤,	Bozn	To To
	Michigan Licens	e No	29239	