## LAND CORNER RECORDATION CERTIFICATE

**SURVEY &** REMONUMENTATION

Filing Requirement of Act 74, Mich. P.A. 1970

NOV 02 1999

or corners in				•	,	1000		
WASHTENAW	Located In:	Corner Code	<del>#</del>		du sècou			
(County)		Sylvan Twp.			SECTION	NC		
. Public Land Survey	T28_R 3E	K-8						
	T R							
	T R					17304		
	TR				11 <b>81-1881</b> -	e: 1 of 2		
2. Property Controlling	\$ T R					25/1999 0 <b>D_17</b> 5		
in Section	S T R		COPY					
B. Miscellaneous	S,T R		— нeg	ister of Dee	us Stamp (	k File Nu	mper	
Property in Sec.	S R			******				_
4. Lot No, R	ecorded Plat		·	A B C	DEF	в н і	JKL	
								_
				2 - 6	\$ <del></del>	┝┋┯┼╸	·};	-
				3	<del>       </del>	<del></del>	1 1 1	_
				⁴┝┆┿	8	1'O	<b>11</b>	2-
I.I. JOHN JEKABSON .	in a field survey on	3 December	, 19 <b>98</b> ,	5	<del>                                     </del>	<del>                                     </del>	+ + +	_
do hereby certify that under req in lines 1 and 2 above were in	uirements of P.A. 74, Michigan P. conformance with regulations	and rules therefore as	required in the	6 - 18-	17-1-16-	-15	14	3-
current manual of survey instru	ictions of the United States Dep	artment of the Interior,	Bureau of Land	7	┼┼┼┼	<del></del>	╂┈╂┈╂	-
Management or by a decree of a	Court of Law and/or that the cor	ner points mentioned in	tines 3, 4 and 5	8 19	2021	-22	23	4-
above were in conformance with	h the rules of the Michigan Boar e-established, monumented, re	d of Land Surveyors or I	oya Decree or a ered found as	9	<del></del>		1-1-1	_
expressed below:	e-established, monthichted, n	a-monumented; 1000N	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1030	2928	27	26	5-
· ·	orners, all in the same town	and range, may be a	ecorded	11			+	_
on this certificate.				1231	3233	34	3536	6-
·				13				_
<ul> <li>A. Description of original r</li> </ul>	monument and accessories a	and/or subsequent re	estoration:					
1824 G.L.O JOHN M. N	MACK SET POST	•	White Oak, 15" White Oak, 14"			0.78Chs. 0.12Chs.		
			White Oak, 14		N 30-E	0.12Cns.		
1948, 9 Dec. HERALD F. HAMIL			2" Oak (Crossed	out written				
SURVEY OF PRESENT CHRYSI PROVING GROUNDS PROPER		louble the distance on the North & South	Hickory) 12" Elm		West West	101.0 182.7	1 2	
PROVING GROUNDS PROFER		3 to existing fence on	5" Oak(Crossed o	out written	AACSI	102.7	2	
	the North & South 1	/16 line on the East	Hickory)		East	132.6	3	
	side of Section 23.							
SEE BACK OF THIS SHEET (NE FOR CONTINUATION OF SECT	ION "A"							
B. Description of corner e	vidence found and/or metho	d applied in restoring	g or reestablishing	corner:	. 484			
					ALLE OF	MICA	4	
	State the annual state of the s	+ @ 18/+						
	field, it separates two farms in an E iben Lesser & Lloyd Grau, told us ti			***	9/	IONN ,	\\ * 3	
30 years ago there was an old Pos	t in the approximate location, Becar	use of tilling and		<i>3</i>	*/ IEK	IOHN ABSON	<b>N</b> 3	É
plowing of the field, no evidence of	this could be found. We used Han	nill's Survey of			PROFI	essiona	- 15	ŧ
the Chrysler Proving Grounds to re & K-9). This checks with State Hid	eestablish this point (distances and hway Dept, and a 1953 Atwell-Hick	angle using 12*/ (S SURVey		\$ 5	SUF	WEYOR No.	JŽŠ	Ė
(Distance from Center of Section a	and extension of fence line.) We se	et 1"x36" from		2666988888884444887	PROFI SUF	9836	NOVE YOUR	•
Pipe with Remon Cap. Also set two	o 6' steel fence posts East & West	of the Pipe.		3	10		10 X	

No. 19836 POFESSION

C. Description of monument for	corner and accessories established to	perpetu	ate locatin	ng the posit	ion of the corner:
Set 1"x36" Iron Pipe with Remon Cap	SW corner of House #2433 - M52		1143.52	4	
	SE corner of House #2433 - M52	N 85°E	1172.66	5	
	NE corner of Pole Barn (N. sd.=192.2')	S 53°E	949.60	6	
	NW corner of Pole Barn (N. sd.=192.2")	S 45°E	796.04	7	
_	Set %" Re-Bar w/Cap, on E&W 1/4 line (as				
	monumented) & West of Highway M-52	East	987.56	8	t . wan da

Legend: Mag & RT = Magnetized Nail & Washtenaw Co. Remon. Tag Indicates Previously Used

I conclude that after careful study of the record documentation and field observations, that this corner is accepted as the best available evidence of the pesition of the original corner.

		Jefo Marie		00 Danasahan	4000
Oleman bur	Charles In	theon	Date	22 December,	1998

Surveyor's Michigan-License No. 19836

CO. REP

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

CONTINUATION OF SECTION 'A'

1953, 20 Oct. 1956

ATWELL-HICKS, INC.
MICHIGAN STATE HIGHWAY DEPT.

3134

I - 94 Freeway NW 1/4 Sec 13

No Indication from Pipe & Stone on E & W fence line

2" Oak
12" Elm
5" Oak
No Witnesses
2" Oak
12" Elm
12" Elm
5" Oak

West West East

101.0 182.7 132.6

야 V -

2664.68 South of K-7

West East

101.0 182.7 132.6

ب بر ب

as per Survey Not Recovered

1972, 29 Aug.

WASHTENAW ENGINEERING CO., INC. NORMAN N. FAHRNER #17620

8924

1948

WASHTENAW CO. ROAD COMMISSION Grid Book Hand Written - "SUTTON 1948"

COMPANY SURVEYOR & P.S. #

JOB. # | P.A. 74 L.C.R.C.

OF SURVEY DESCRIPTION LOCATION | MONUMENT

WITNESSES

& DISTANCE BEARING

D#

COMMENT

Iron Pipe

1998 WASHTENAW COUNTY REMONUMENTATION PROGRAM

SYLVAN TOWNSHIP TOWN 2 SOUTH, RANGE 3 EAST K-8 (1/4 CORNER COMMON TO SECTIONS 23 & 24)

History compiled by:

I. John Jekabson P.S. # 19836 Roskelly, Jekabson & Assoc. P.C.

Legend:
Indicates Previously Used

- Washtenaw Co.

5017304 Fase: 2 of 2 02/25/1999 02:59P L-2 P-176

图》

SURVEY & REMONUMENTATION

NOV 02 1999

**SECTION**