## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

## SECTION

For corners in  Washtenaw (County)	Located In:	Corner Code #					
1. Public Land Survey	T <u>2S</u> R <u>5E</u> T R T R	J-13		P: Ø:	794736 age: 1 of 2 2/07/2000 0	2 82 : 55P	,
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous</li></ul>	S T R S T R S T R	Peggy M. Haine	s - Washtenaw		of Deed Star	np & File	e Numbe
Property in Section  4. Lot No, Ro	S T Recorded Plat		1 A B C	D E F	G H I	J K	L M
I, Thomas L. Sutherland under requirements of P mentioned in lines 1 and rules therefore as require United States Department decree of a Court of Law and 5 above were in cortain Land Surveyors or by a monumented, recovered	I, in a field survey on 11-8-1999.  A. 74, Michigan P.A. of 1970, the second of the current manual of surveint of the Interior, Bureau of Landward/or that the corner points manual of the Mormance with the rules of the Moreover of a Court of Law; estable, found as expressed below:	do hereby state that he corner points with regulations and ey instructions of the d Management or by a entioned in lines 3, 4 Michigan Board of olished, re-established,	3	17 - 16	22 -	-14 -14 -23	- 13 - - 13 - - 24 -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			12 - 31 -	- 32 33	34	- 35 <b>-</b>	- 36 <b>-</b>
A. Description of origin	nal monument and accessories and	Vor subsequent resortation	on: 13				

- 1) 18" W.O. N69°W 44 Links
- 2) 24" W.O. S77ºE 36 Links

Continued on Back

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" Rod in monument box. Set aluminum remonumentation cap stamped 24620 over 3/4" rod in monument box.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - 3/4" Iron rod with aluminum remonumentation cap stamped 24620 in monument box
  - 3) S.W. corner stone porch N30°E 126.35
  - 5) 22" Hickory N40°W 93.62 to remon tag on S.W. side
  - 6) 1/2" iron pipe (no cap) North 33.00
  - 7) Iron Pipe (A-H 6998) South 32.95
  - 9) Power Pole S69°W 77.38 to remon tag on N'ly side
  - 10) N 1/4 Corner Section 2, Lodi Twp. (3/4" iron pipe in mon. box) East 54.30
  - 12) 20" Spruce N8ºE 44.86 to remon tag on West side
  - 13) 14" Twin Elm N5°W 49.18 to remon tag on East side
  - 14) 9" Box Elder N10°W 24.51 to spike on East side
  - 15) Power Pole S76ºE 118.14 to Nail on N'ly side


I conclude after careful study of the record documentation and field observation, that this corner is accepted as the best available evidence of the position of the original corner. This corner is not common to J-1, T35, R5E.

SUTHERLAND Surveyor's Michigan License No.

## A. Continued

W.C.R.C., W.J. Armstrong #2444, 5/1/32, Grid Book From J.B. Davis witness tree found the trace of an old wood stake in the center of a pile of stones and bricks. Reset with iron pipe, stones, and bricks.

- 3) S.W. corner stone porch N30 1/2°E 126.4
- 4) 4" Apple S57°W 49.2
- 5) 18" Hickory N37°W 94.0
- 6&7) 2 Right of Way Pipes



- 8) Guard Post N75°W 74.20 to Nail
- 9) E. Pole S69°W 77.29 to Nail

W.C.R.C., No Date, Grid Book (handwritten - Lodi Twp. Witnesses)

10) N. 1/4 Lodi Twp. is 54.4 East of S1/4 Post Sec. 35 Scio Township

Atwell-Hicks, Taft, 4/29/56 Found 1 1/2" Iron 2' Deep. Set 1/2" iron pipe on top 6" below surface

- 5) N39°W 93.6 to 15" Hickory
- 11) N66°W 52.4 to 10" Elm
- 12) N8ºE 44.7 to 6" Pine

Atwell-Hicks, R.J. Jagow # 6998, 7/23/75 L.C.R.C., Liber 4, page 33 - P.V. Schwimmer #24618, 8/20/77, Survey 505-38

1/2" Rerod in monument box

- 10) N 1/4 Cor. Sec 2 E'ly 50.31
- 12) 14" Blue Spruce N18ºE 44.7
- 13) 12" Twin C. Elm North 49.8
- 5) 18" Shag Hickory N40°W 93.6

Washtenaw Engineering, N.N. Fahrner #17620 5/27/81, L.C.R.C., Liber 6, Paage 151 - T.L. Sutherland #24620, 6/2/81, Survey R-4735

1/2" Iron pipe in monument box

- 5) 18" Hickory N37°W 94.0
- 9) Power pole S69°W 77.29 to Nail
- 12) 12" Pine N10°E 44.49 to Nail

Ayres, Lewis, Norris, and May, C.C. Wilson # 13604, 9/20/85, Survey 82252-01

1/2" Iron rod in monument box

- 12) 14" Blue Spruce N18ºE 44.7
- 13) 12" Elm N'ly 49.8
- 5) 18" Shag Hickory N40°W 93.6

Land Surveying Consultants, R.T. Tietsiema # 20712, 9/4/87, Survey 13-03687-2S5E35

- 5) 16" Hickory N39°W 93.6
- 11) 12" Elm N66°W 52.4
- 12) 9" Pine N08ºE 44.7

Washtenaw Engineering, N.N. Fahrner #17620 5/16/97, Survey R7376

3/4" Rod in monument box

- 12) 18" Pine N10ºE 44.44 to Nail
- 14) 8" Box Elder N10°W 24.55 to Nail
- 10) N 1/4 Cor. Sec. 2, Lodi Twp East 54.26



02/07/2000 02:55P

REN

- 2006

SECTION