

**SURVEY &
REMONUMENTATION**

**MAY 09 1996
COMMISSION**

**REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

-copy-

REGISTERED
 WASHTENAW COUNTY, MI
 MAR 29 1 31 PM '96
 PERCIVAL JAMES
 COUNTY CLERK/REGISTER
-copy-

For corners in

<u>Washtenaw</u> (county)	Located In:	Corner Code #
1. Public Land Survey	T <u>3S</u> R <u>3E</u>	<u>K12</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, R.T. Tietsema, in a field survey on May 31, 19 95, do hereby certify that under the requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with the regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

1815	GLO (Wampler)	Fld. Notes	Set Original Corner	1) 10" Hickory	S21W	1.28 chains (84.4
			Set 1/4 Section Post	2) 20" W. Oak	N16E	71 links.(46.86')

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron Pipe
Also found remaining witnesses:

5) Centerline Pvmt.	West	17.5'
6) Mail Box	S05E	19.1'
12) U. Pole	N85W	42.13' to nail & R.T.
14) East Edge of Pvmt.	West	4.0'
15) 24" Fir	N30E	103.5' to nail & R.T.
16) 24" Maple	South	141.50' to nail & R.T.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Cap
Also found remaining witnesses:

5) Centerline Pvmt.	West	17.5'
6) Mail Box	S05E	19.1'
12) U. Pole	N85W	42.13' to nail
14) East Edge of Pvmt.	West	4.0'
15) 24" Fir	N30E	103.5' to nail
16) 24" Maple	South	141.50' to nail

It is our opinion that this corner represents the original corner and is accepted as the best available evidence of the position of the original corner.

Signed by *R. Tietsema* Date 11 Dec. 95
Surveyor's Michigan License No. 20712

- Copy -

Section A continued

Date	Name	Address	Notes	Witnesses	Measurements
2/26/1970	Atwell-Hicks		Set 3/4"x18" Iron Pipe		3) 28" Maple South 61.04' to spike on west side. 4) 42" Maple S15E 22.01' to spike on west side 5) Centerline of Asphalt West 17.7' 6) Mail Box Hse #10475 South 15.8' 7) 3" Steel Fnc.Post East 10.64' 8) 22" Pine S30E 109.6'(S end of ROW) 9) 18" Pine S55E 88.0' 10) 24" Pine S80E 70.1'(N end of ROW)
2/21/1971	N.N.Fahrner JOB NO:6910	17620 LIP89	Boundary	Fnd 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
2/14/1972	N.N. Fahrner JOB NO:7844	17620		Fnd 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
11/7/1972	Washtenaw Engineering JOB NO:9440		Boundary		No Witnesses Given
2/16/1977	R.T.Tietsema JOB NO:7-77		Boundary		11) 18" Fir N30E 135.5' 10) 20" Fir S70E 70.0' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
7/26/1977	W.F.Lewis JOB NO:14954	14336	Site Plan		No Witnesses Given.
8/29/1977	N. N. Fahrner JOB NO:15236	17620	Boundary	Fnd. 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
4/19/1979	N. N. Fahrner JOB NO:16785	17620	Boundary	Fnd. 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
10/10/1979	N. N. Fahrner JOB NO:17141	17620	Boundary	Fnd. 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
3/24/1982	R.T. Tietsema JOB NO: 282	20712	Boundary	Fnd Iron Pipe	10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder
12/5/1983	R.T.Tietsema	20712	Boundary		No Witnesses given
8/10/88	Craig Eckfeld JOB NO: 88242	33135	Boundary	Fnd 1" Iron Pipe	10) 24" Pine S75E 70.0' to nail 12) U.Pole N75W 42.08' to nail 14) E. Edge of Asph East 3.8' 15) 20" Pine N18E 103.5' to nail 16) 20" Maple S04W 141.21' to nail
4/6/1989	N. N. Fahrner JOB NO:8681	17620	Boundary	Fnd. 1" Iron Pipe	4) 30" Maple S20E 22.0' 7) Steel Fnc.Cor Post S85E 10.7' 10) 20" Fir S70E 70.0' 11) 18" Fir N30E 135.5' 12) Telephone Pole N75W 42.0' 13) Edge Pvmt.in M-52 East 7.2' in gravel shoulder

APPROVED

DATE 10/23/95

CO. REP. [Signature]