SUHVEY & REMONUMENTATION

Liber 00001 Page 0431

MAY 0 9 1996

COMMISSION

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

-copy-

For corners in	.						
Washte	enaw unty)	Located In:	Corner Code	e #	1 000	••••	
1, Public Land	i Survey	T 3S R 3E T R T	K13			February CZ	7a
2. Property Co in Section 3. Miscellaneo Property in	S S	T R T R T R T R T R T R T R T R T R T R			ister of Deeds Stamp	31 See Nuring	iber
	Recorded					8	inque eriba Anno
do hereby cer points mentio therefore as Department o and/or that the the rules of t established, re	tify that under the ned in lines 1 and 2 required in the cur f the Interior, Bures e corner points mented Michigan Board established, monte	requirements of P 2 above were in co rrent manual of s au of Land Manag ntioned in lines 3, d of Land Survey amented, recovered	A.74, Michiga onformance wit survey instruct jement of by a 4, and 5 above ors or by a C d. found as exp		r 5 6 7		
	corded on this c		Same town	and range, may be			
A. Description	on of original mon	nument and acces	ssories and/o	r subsequent restoration:			•
1815	GLO (Wampler)		Fld. Notes	Set Corner of Sections 35 &	No Witnesses Give 36.	n.	
1935	W.J. Armstrong	L2P453	·	Fnd. 3/4" Iron Pipe Set in Cone. with a great mass of stones around it.	1) 24" Elm 2) 18" W. Oak 3) 15" W. Oak 4) 30" Y. Oak	N02E N80E South N89W	17.8° 5.5' 13.3' 38.8'
(Continued on bath B. Description	ack) on of corner evide	ence found and/o	r method app	lied in restoring or reesta	blishing corner:		٤
	ipe in Concrete and surro	ounded by large stones					•
	Stump Cor. Sec. 2, Manchester	N80E East N85W	5.5° 7.0° 17.48°				٠
						:	* 1
	1						
C. Description	on of monument f	or comer and ac	cessories esta	ablished to perpetuate lo	cating the position	of the co	rner:
5) NE 9) 16 11) 30 12) 14	essories: k Stump Cor. Sec. 2, Manchester Maple Oak Maple	N85W 830W N05E	5.5' 7.0' 17.48' to nail & 1 39.13' to nail & 1 27.64' to nail & 1	R.T. R.T.			
It is our opinion th	ne this corner represents t	he original corner and is	a careful and faith	ful pernetuation of the position of the	ne original corner.		

Signed by Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAI REVISED MA

ection A continued	1 .			•		•			
22/1970	Atwell-Hicks			:		. 2) 22" W. Oak 5) NE Cor Sec 2	N80E	5.0'	-
						T4S,R3E 6) Fence line	East SW	7.03' (3/4" I 2'	ron Pipe)
						7) N/S Fence line 8) 4" Oak	West S10W	4.5° 4.5	
<i>1</i> 27/1972	N.N.Fahmer	17620	L2P453		3/4" Iron Pipe in Conc.	2) 24" W. Oak 5) NE Corner Sec 2	N80E	5.5'	
·						Manchester 9) 12" Maple 10) 8" Maple	East N85W S07W	7.0° 17.4' 11.2'	
1 <i>/7/</i> 19 77	Washtenaw Engineer	ing		Boundary		No Witnesses given			
/24/1976	JOB NO:9440 R.T. Tietsema	20712	· .	Boundary		No Witnesses Given	•		
	JOB NO:131-76			•	•				
/13/1987	R.T. Tietsema	20712		Field Notes Fld. Book #21 P56	Fnd. 3/4" Iron Pipe	5) NE Cor Sec 1, T4SR3E	East	7.03'	
/06/1987	R.T. Tietsema JOB NO: 10187	20712		Sketch of Survey		5) NW Cor Sec 2, T4SR3E	N89-14-4	19E	6.97
:/6/1989 :	N. N. Fahrner	17620		Fnd. 3/4"Iron Pipe in Conc.	2) 24" W. Oak 5) NE Corner Sec 2	N80E	5.5'		
	JOB NO:8681					Manchester 9) 12" Maple 10) 8" Maple	East N85W S07W	7,0' 17,4' 11,2'	
•	•					, .	N80E	5.5*	
:/ 22 /1990 -/	Lawrence O'Donnell JOB NO:22832	28419		Boundary	Fnd. 3/4"Iron Pipe in Conc.	2) 24" W. Oak 5) NE Corner Sec 2			
	JOB NO:22832			,		Manchester 9) 12" Maple	East N85W	7.0' 17.4'	
		1				10) 8" Maple	S07W .	11.2'	

APPROVED

DATE 10/23/ CO. REP.