


MICHIGAN DEPARTMENT OF CONSERVATION
FULLER LAKE

AREA 12 ACRES
 BENZIE COUNTY T. 27 N., R. 13 W., SEC. 15
 SURVEY AND SOUNDINGS FEB. 5,-FEB. 7, 1963

B.M. No. 2=1007-SPIKE IN BASE
 OF 10" WHITE PINE
 WATER SURFACE ELEVATION=97.8
 2/7/63

B.M. No. =1000-SPIKE IN BASE
 OF 36" WHITE PINE
 WATER SURFACE ELEVATION=97.8
 2/7/63



LEGEND

BOTTOM

□ Organic

SHORE FEATURES

- ~ Encroaching shore
- ⊙ Wooded
- ⊙ Partly wooded
- ⊙ Cleared
- ⊙ Marsh
- Building
- Unimproved road
- Inlet or outlet

