


B.M. 100-0-R. R. SPIKE BASE
 OF 24 IN. DIA. OAK.
 NORTH SIDE LAKE.
 LEVEL BELOW
 1&I CABIN.
 WATER SURFACE ELEV.: 96.5
 2/28/44

INSTITUTE FOR FISHERIES RESEARCH
 DIVISION OF FISHERIES MICHIGAN CONSERVATION DEPT.
 LAKE INVENTORY MAP
MILL LAKE
 AREA 142 ACRES
 MARGINAL SURVEY AND SOUNDINGS 2/9,10,11,12,14,15/44
 VEGETATION PLOTTED 8/14/44
 WASHTENAW COUNTY T. 2 S., R. 3 E., SEC. 4-5



- LEGEND**
- BOTTOM**
- Sand
 - ▨ Marl
 - ▩ Marl and Detritus
 - Marl and Luck
- OUTLINE & CONTOURS**
- Shoreline
 - - - Contours
- SHORE FEATURES**
- Cottage
 - ≡ Slope
 - ⊙ Gravel
 - ⬇ Brush
 - ∨ Marsh
 - ⋯ Unimproved road
 - Improved road
 - - - Trail
 - Boathouse
 - ⊙ Wooded
 - ⊙ Partly wooded
 - ⊙ Cultivated
 - ⊙ Pasture
 - ⊙ Inlet
 - ⊙ Outlet
 - ⊙ Deadhead
 - ⋯ Encroaching shore
- VEGETATION**
- T Floating
 - I Emergent
 - Submergent

