

SURVEY & REMONUMENTATION

FEB 20 2001

MECOSTA COUNTY REMONUMENTATION PROGRAM

SECTION

CORNER APPROVED BY PEER GROUP ON September 8, 2000

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Mecosta (County) Located in: Mecosta Twp. Corner Code #

200000007746 Filed for Record in MECOSTA COUNTY, MICHIGAN JOANNE BROWN On 10-27-2000 At 09:20:24 am. REMON COR 11.00 OR Liber 101 Page 346 - 347

- 1. Public Land Survey SEC 16 T 14N R 10W E-6
2. Property Controlling in Section S
3. Miscellaneous S
Property in Sec. S

Instrument 200000007746 DR 101 346 Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, James J. Keller, in a field survey on June 7, 20 00 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- March 1, 1838, Abner E. Van Ness, Deputy Surveyor GLO "Set Gr. Sec. Post" 18" Beech N32°E 16 Links (10.56')
December 13, 1926, William Fargo, C/Co Surveyor, Dwg No F-5618 "Proxated. Set Tile" 39.88 ch North to NW Corner (2632.08') and 39.88ch South to SW Corner (2632.08') 10" Maple N20-3/4°E 1.28-1/4 ch (84.645')
June 13, 1979, Norman L. Ochs, RLS #22439 (LCRC L1 P487) "Set 1/2" Pipe & Cap 1/2 way E on line between the NE & SE corners" 6" R.Pine 80.42' 6" R.Pine N41°E 40.26'
June 7, 2000, James J. Keller, RLS #10693, (FB 134-N P35) "Found 1/2" pipe bent North 2" deep, 8' East of C/L gravel road." Found 60d N sd P.Pole N85°W 80.62' Found 60d NW sd 12" R. Pine N45°E 40.26'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

- June 7, 2000, James J. Keller, RLS #10693, "Found 1/2" pipe bent North 2" deep Found bent 60d N sd P.Pole N85°W 80.62' Found 60d NW sd 12" R. Pine N45°E 40.26' C/L gravel road West 8'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted 1/2" pipe & set Remonumentation Monument over it as best available evidence of the position of the original corner.

- Set 60d and tag above bent 60d N sd P.Pole N85°W 80.62' Set 60d and tag N3 sd 12" Cherry N35°W 59.85' Set 60d and tag NW sd 12" R. Pine N45°E 40.26' Set 60d and tag S sd 12" R. Pine S70°E 26.92' C/L gravel road West 8' C/L 2 track to West, North 12.5'



APPROVED BY MECOSTA CO. PEER GROUP IN ACCORDANCE WITH P.A. 345 of 1990 James J. Keller CHAIRMAN DATE SEPT. 8, 2000

Signed by James J. Keller Surveyor's Michigan License No. 10693

Date September 12, 2000

Grid table with columns A-L and rows 1-13. A dot is present at row 6, column G.