

**A. DESCRIPTION (cont.)**

William Tingley, R.L.S. # 30104  
April 10, 1989  
Set ½" Iron and cap by prorating 1909 Survey by Jacques. Corner is at the end and centerline of roads.  
#3 Wood Fence Post West 22.7' Northerly side  
#4 10" Pine S45°E 29.92' Northerly side  
#5 24" Maple S45°W 41.44' Westerly side  
#6 Pipe Line Post S10°E 35.35' Face

Norman L. Ochs, R.L.S. # 22439  
Drawing No. 90228B January 22, 1991  
Found ½" Rod and Cap #30104  
#3 Wood Fence Post West 22.7' Northerly side  
#4 10" Pine S45°E 29.92' Northerly side  
#5 24" Maple S45°W 41.44' Westerly side  
#6 Pipe Line Post S10°E 35.35' Face

Field Notes for job number: 98312 February 10, 1999  
Found ½" Rerod with cap # 30104 April 10, 2001  
Drawing No. 01034D and field notes  
Reset ½" x 18" Rerod with cap # 22439 holding previous measurement and distance between points 1 and 2. This position agrees with remaining witnesses. The ½" Rerod with cap # 30104 set by Tingley that was found on February 10, 1999 was gone. May have been removed by property owner. Witnesses same.