



DELIVERED TO NEWAYGO CO.  
02/01/2013 4:30:35 PM

2012 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Newaygo  
(County)

Located in: Corner Code #

**VOL. 7 193**

- 1. Public Land Survey  
T15N R11W I-10  
T N R W  
T N R W  
T N R W  
T N R W
- 2. Property Controlling in Section S  
S  
S  
S
- 3. Miscellaneous Property in Sec. S  
S  
S  
S



LINDA M. LANDHEER  
NEWAYGO COUNTY REGISTER OF DEEDS  
RECEIVED AND RECORDED  
02/01/2013 4:36:39 PM

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Norman L. Ochs, in a field survey on September 17, 2012 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.**

One Quarter Corner common to Sections 26 and 27, T15N R11W, Norwich Township.

**A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:**

- GLO -resurvey
- Milton Nye, 3<sup>rd</sup> quarter 1856
- Re established old quarter section post
- #1 10" Yellow Birch N25°E 6 links (3.96')
- #2 10" Black Ash N80°W 6 links (3.96')
- Newaygo County Road Commission Sheet 1950's±
- Iron
- #4 Fence Post S88°W 35.05'
- #5 Power Pole N52°W 62.75'

William M. Jacques, County Surveyor  
Book 24, Pages 19 and 20 March 21, 1911  
Iron Stake  
Book B, Pages 54 and 55 April 21, 1912  
Stake  
#3 14" Pine Stump S22°W 7 feet


**B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:**

I found 3/4" x 3/4" x 20" Iron 36"± below grade that was raised with a 3/4" x 18" Iron Pipe to 6"± below bituminous. The centerline of a North and South bituminous road is 2'± West. No apparent occupation to East. The corner is online with a fence to the West. The condition of the witnesses are as follows: #1 thru #3 gone, #4 found 10" wood fence post (leaning Southwesterly) S85°W 35.3'± to center, #5 in good condition.

**C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:**

I removed the both Iron and set a 4" diameter Harrison Cast Iron Monument 20" long marked "County Surveyor # 22439", flush with bituminous and grouted in place as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner.

- #5 Power Pole N54°W 63.26'
- 16" White Pine S53°W 104.02'
- 14" Willow N20°E 68.92'
- 4" Elm S28°E 37.75'



Signed by Norman L. Ochs Date JANUARY 31, 2013  
Norman L. Ochs

Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Approved by Peer Review Group on August 14, 2012  
Norman L. Ochs, County Representative.

*N. L. O.*

Revised May 14, 1975  
Revised Jan., 1983