

SURVEY & REMONUMENTATION

MAR 16 2005



LINDA M. LANDHEER  
NEWAYGO COUNTY REGISTER OF DEEDS  
RECEIVED & RECORDED  
02/26/2005 9:26:27 AM

2004 Newaygo County Remonumentation Project  
SECTION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Newaygo  
(County)

Located in: Corner Code #

VOL. 4 270

1. Public Land Survey

T15N R11W

K-6

- T N R W
- T N R W
- T N R W
- T N R W
- T N R W
- T N R W
- T N R W
- T N R W

2. Property Controlling

S

in Section

S

Miscellaneous

S

Property in Sec.

S

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Norman L. Ochs, in a field survey on May 28, 2004, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Quarter corner common to Section 13 and 14, Norwich Township, Newaygo County.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO John Allard  
1837

#1 12" Beech N50°W 15 links (9.9')

#2 12" Beech S21°E 21 links (13.86')

GLO Milton Nye Resurvey

3<sup>rd</sup> Quarter 1856

Reestablished old Quarter Section Post

#1 12" Beech N50°W 15 links (9.9')

#2 12" Beech S17½°E 28 links (18.48')

OVER\$

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 6" concrete cylinder with brass cap (Robert A Griffin Monument) at ± 1.5 above grade. The corner is on woods line running South and East. The condition of the witnesses are as follows: #1 and #2 are gone, #3 in good condition, #4 found spike in NW side of 18" Red Oak N63°E 35.20' (dead), #5 and #6 in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted Robert A Griffins 6" concrete cylinder monument with brass cap marked "¼ S 14/S 13 1963" at ± 1.5 above grade as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the position of the original quarter corner.

#3 32" Red Oak N53°W 11.27'

#5 20" Red Oak S30°E 42.10'

#6 2' x 2' gray stone N50°E 103.54'

10" White Oak S67°W 62.75'

Found spike in SW side

Found spike in NE side

Found "X"

Set 40d spike with tag in South side

Signed by

*Norman L. Ochs*

Norman L. Ochs

Date July 27, 2004

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971  
Revised May 14, 1975  
Revised Jan., 1983

Approved by Peer Review Group on July 20, 2004

Norman L. Ochs, County Representative.

*N.L.O.*

