



DELIVERED TO NEWAYGO CO
02/06/2015 12:28:34 PM

2014 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

- 1. Public Land Survey
T14N R11W C-10
T N R W
T N R W
T N R W
T N R W
- 2. Property Controlling in Section
S
- 3. Miscellaneous in Section
S
S
S

VOL 8 74



STEWART K SANDERS
NEWAYGO COUNTY REGISTER OF DEED
RECEIVED AND RECORDED
02/06/2015 12:30:23 PM

Register of Deeds Stamp & File Number

- 4. Lot No. _____ Recorded Plat _____
- 5. Private Claims _____

I, Norman L. Ochs, in a field survey on October 6, 2014 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

One Quarter Corner common to Sections 29 and 30, T14N R11W, Goodwell Township

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - Resurvey
 J.H Mullett, November 18, 1837
 Set quarter section post
 #1 10" Lynn S25°E 16 links (10 56')
 #2 12" Hemlock N75°W 8 links (5 28')

Robert A Griffin, R L S. # 13584
 LCRC # 651
 October 30, 1984
 Set Monument 1" x 60" Iron Pipe with brass cap - measured NW corner Section 29, N00°20'06"W 2623.78'. Measured C¼ Corner Section 29, N89°05'12"E 2619.71'
 #3 12" Hemlock S10°E 51.36'
 #4 12" Hemlock S14°W 30 19'
 #5 12" Hemlock N47°W 14.24'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER.

I found a 2" Galvanized Pipe with a 3" brass cap with #13584 (Robert A. Griffin), projecting 22"± above grade No apparent occupation to the North, South, East and West. The condition of the witnesses are as follows: #1 and #2 gone; #3 in good condition, #4 found 60d spike on East side of dead 12" Hemlock with blazes and bearing tree tags S14°W 30.23', #5 in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:


I accepted the 2" Galvanized Pipe with 3" brass cap # 13584 (Robert A. Griffin) projecting 22"± above grade as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner.

- #3 18" Hemlock (with blaze & tag) S10°E 51.23' Found 60d spike on East side
- #5 16" Hemlock (with blaze & tag) N47°W 14.24' Found 60d spike on NE side
- 18" Hemlock (with tag) S85°E 86 51' Set 40d spike and tag on North side
- Hemlock (with tag) S30°E 31.54' Found 40d spike on SW side
- Found Carsonite Post East 1.23'

Signed by Norman L. Ochs Date February 6, 2015
Norman L Ochs

Surveyor's Michigan License No 22439 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan , 1983

Approved by Peer Review Group on September 30, 2014
Norman L Ochs, County Representative



M.L.O.