REC'D FEB 10 2006

2005 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY & REMONUMENTATION
FEB 28 2006
VOL. 5 SECTION 58

For corners in Newaygo (County)

	Located in:		Corner Code #
1. Public Land Survey	T13N	R11W	K-5
	T N	R W	
	T N	R W	
	T N	R W	
2. Property Controlling	S___ T N	R W	
in Section	S___ T N	R W	
3. Miscellaneous	S___ T N	R W	
Property in Sec.	S___ T N	R W	

LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED & RECORDED
02/10/2006 12:14:42 PM
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Norman L. Ochs, in a field survey on July 29, 2005, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Section corner common to Section 11, 12, 13 and 14, Big Prairie Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO – James H. Mullett
1837
Set post corner
#1 8" White Oak N49°E 50 links (33.0')
#2 10" White Oak N67°W 35 links (23.10')

Lyle S. Shepherd, RLS #503
May 18, 1925
See Book 59A page 22 & 4
Dug Found old stake crockery around
#3 12" Black Oak N53°E 72 links (47.52')
#4 16" Black Oak S52½°W 106 links (69.96')

OVER↳

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a Concrete Monument at ± .6 below grade. The corner is in the centerline of bituminous road to the West. The centerline of North-South gravel road is 7' East of the corner. The condition of the witnesses are as follows: #1 and #2 are gone, #3 in good condition, #4 and #5 are gone, #6 found PK nail in SW side of 12" White Oak S40°E 65.05, #7 found PK nail in SW side of 10" stump N40°W 66' center, #8 thru #10 are in good condition, #11 found twin stump N30°E 62.30' center, #12 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted the Concrete Monument at ± .6 below grade as a substantial marker for the Section corner and is accepted and a careful and faithful reestablishment of the position of the original Section corner.

#3 22" Black Oak N53°E 47.25'
#8 24" Maple S40°W 40.10'
#9 Light Pole East 23.43'
#10 16" White Oak S45°E 60.81'

Set 40d spike with tag in SE side
Found PK nail in SW side
Found PK nail in North side
Found spike in SW side

Signed by Norman L. Ochs
Norman L. Ochs

Date December 23, 2005

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on September 13, 2005
Norman L. Ochs, County Representative.
N. L. O.

STATE OF MICHIGAN
NORMAN L. OCHS
LAND SURVEYOR
No. 22439
REGISTERED LAND SURVEYOR