

**SURVEY & REMONUMENTATION**

AUG 06 2008

**SECTION**

**OSCODA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970



JERI WINTON  
OSCODA COUNTY

For corners in

OSCODA (County)

Located In: Corner Code #

1. Public Land Survey

T26N R1E D-5

2. Property Controlling

S

3. Miscellaneous

S

Property in Sec.

S

4. Lot No. \_\_\_\_\_, Recorded Plat

5. Private Claims

**APPROVED**

County Remonumentation

Peer Review Group

*NCC 18 JULY 08*

REGISTER OF DEEDS

07/29/2008

FEE:

PAGES: 2

RCPT#: 8285

09:33:02AM

\$17.00

LC8-146

CORNER RECORDATION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	6	5	4	3	2	1						
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Marvin E. Myers, P.S., in a field survey on Jan 10 20 08 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

**D-5 Quarter Section Corner common to Sections 8 & 17 T26N-R01E.**

1839 GLO William R. Coon Deputy Surveyor

Mon - Set quarter Section post

Wit: Spr. Pine 4" S34°W 5 lks (3.30')

Spr. Pine 4" N11°E 13 lks (8.58')

1937 USGLO Dependent Resurvey James T. Boyd and T. Nolan Canada, Transitman, Guy Veal, CE  
Mon - Set concrete monument 24" long, 6" diam, 26" in the ground with 3 1/2" diam brass tablet with 3" stem embedded in top by proportionate distance.  
Wit: 6" Poplar N21°30'E 20 lks (13.20') marked "1/4 S 8 BT"  
8" Poplar S42°W 60.5 lks (39.93') marked "1/4 S 17 BT"

Part A continued on back of sheet →

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**D-5 Quarter Section Corner common to Sections 8 & 17 T26N-R01E.**


Found a USGLO concrete monument with a brass cap in good condition under East-West fence line, left in place and set 2 nails alongside the monument for magnetic attraction; N31°E 84.20' found 19" Oak; S10°E 21.51' found 14" Maple; South 23.00' found 14" Oak. Set nails and tags in the above witnesses. Accepted USGLO concrete monument as a careful and faithful reestablishment of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**D-5 Quarter Section Corner common to Sections 8 & 17 T26N-R01E.**

Mon - USGLO concrete monument with a brass cap in good condition. Set 2 nails alongside the monument for magnetic attraction.

- Wit: N31°E 84.25' Set nail & tag in West side of 19" Oak.
- S10°E 21.37' Set nail & tag in East side of 14" Maple.
- South 23.15' Set nail & tag in West side of 14" Oak.
- N05°W 58.51' Set N&T in West side of 13" Red pine.
- N72°W 4.1' Face of 8" Fence corner post.
- S38°W 1'± Cedar post with USFS location tag.
- South 2'± Set Carsonite post.
- North 20'± C/L of East/West Power line.
- West 108'± C/L of North Power line.



Signed by Marvin E. Myers

Date July 14, 2008

Surveyor's Michigan License No. 31600