



8 0 1 2 5 5 5  
 Tx:4008638  
 8/26/2020 2:20:00 PM  
 220-02159  
 Filed for Record in  
 OSCODA COUNTY MICHIGAN  
 JERI WINTON  
 REGISTER OF DEEDS  
 08/26/2020 02:56 PM  
 PAGES: 2

**Land Corner Recordation Certificate**

Authority: MCL 54.205

Surveyor's Name: Cole A Sorenson, PS No. 59056

Field Survey Date: May 21, 2020

For corner(s) in: Oscoda County

**Original Public Land Survey Corner**

**Corner Code**

S \_\_\_\_\_ T 25N R 01E \_\_\_\_\_ J-03  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

**Property Controlling Corner**

**Corner Code**

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

**Property Corner**

**Corner Code**

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

**Protracted Public Land Survey Corner**

**Corner Code**

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |    |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|----|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   | 1  |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   | 2  |
| 3  |    |   |    |   |    |   |    |   |    | • |    |   |   | 3  |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   | 4  |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   | 5  |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   | 6  |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   | 7  |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   | 8  |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   | 9  |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   | 10 |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   | 11 |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   | 12 |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   | 13 |

**Part A: Corner History**

1839 GLO William R Coon, DS  
 Mon-Set Section Post  
 Wit: 4" Dwarf Oak N38°E 7 lks (4.62')  
 4" Spruce Pine (Jack Pine) S36°30'W 9 lks (5.94')

1929 USGLO Guy R Veal, CE  
 Mon - Set Iron Post 3 feet long 1 in. dia, 27" in ground, with Brass Tablet by proportional distance  
 Wit: 7" Black Oak N52°30'W 14 lks (9.24')  
 6" Black Oak S4°15'W 39 lks (25.74')

1934 USFS LCR by A R Qulliman, Jr. Forester  
 Mon - USGLO Pipe in good condition 8" above ground  
 Wit: 6" Oak N54°W 9 feet marked "1/4 S 2 BT"  
 7" Oak S5°W 24 feet marked "1/4 S 11 BT"  
 Location poster is on an Oak BT tree 6" dia, on the East side of tree from which this corner bears S54°E 9 feet.

1976 USFS LCR by Tom Wimble  
 Mon- Found corner  
 Wit: Set post by corner side of road  
 Could not find 7" Oak bearing tree N52°30'W and put in bearing tree 7" Maple 8/16/76  
 7" Red Maple N78°E 9.4  
 8" Black Oak S4°15'W 39 lks (25.74')